



Industrial Vehicles, Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 5 Tuas Avenue 10 Singapore 632010 Tel: 6861 0007 Fax: 6861 3070
Finance & Trade Account: 18 Singapore 632022 Tel: 6861 0007 Fax: 6862 3400
Website: www.goldbell.com.sg
CR. Reg. No. 198069435

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	XE5826R
Policy No:	DMCVSNW00099622200	Date of Loss:	07/10/2022
Vehicle Reg. No.:	XE5826R	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LBL CONSTRUCTION PTE. LTD.		
Driver:	KARUPPIAH ARIYAKKANNAN		
Make/Model:	mitsubishi fuso, 10.7 D FV70HJD2VDEA (M)	Vehicle Reg. Date:	18/08/2020
Vehicle Colour:	White		
Engine No:	470912C0518410	Chassis No:	FV70HJA10001
Odometer:	0 KM		
Paint Type:			
Total Loss?	YES		
Est. Duration of Repair (day)	45		
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)		

COST OF CLAIMS	Amount
Parts	28,770.54
Miscellaneous Items	4,100.00
Labour	8,900.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	41,770.54
+ GST 7.00% (\$\$)	2,923.94
Nett Amount (\$\$)	44,694.48

This claim is handled by: LIEW SI MING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 Oct 2022)
 MITSUBISHI FUSO 10.7 D FV70HJD2VDEA (M) (Model not available in database)
 Parts: N/A
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Goldbell Engineering Pte Ltd/XE5826R/18/10/2022 11:31
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*CHAMBER,NO.24-24SPG. / <i>Burnt</i>	0.00	0.00	*395.00 F
2	2		*EXPANDER ASSY,FR BRAKE / <i>Burnt</i>	0.00	0.00	*2,994.14 F
3	2		*O-RING,AIR CHAMBER / <i>Burnt</i>	0.00	0.00	*10.30 F
4	1		*SENSOR,RR BRAKE PICKUP,LH / <i>Burnt</i>	0.00	0.00	*300.00 F
5	2		*SPACER,RR BRAKE / <i>Burnt</i>	0.00	0.00	*17.82 F
6	1		*SENSOR,RR BRAKE PICKUP,RH / <i>Burnt</i>	0.00	0.00	*309.00 F
7	1		*COVER A ; DUST / <i>Burnt</i>	0.00	0.00	*156.56 F
8	1		*MODULATOR ASSY,BRAKE / <i>Burnt</i>	0.00	0.00	*3,902.04 F
9	1		*MODULATOR ASSY,BRAKE / <i>Burnt</i>	0.00	0.00	*2,129.36 F
10	6		*JOINT,BRAKE AIR LINE,NO.5 / <i>Burnt</i>	0.00	0.00	*418.92 F
11	2		*JOINT,FRAME BRAKE AIR LINE,NO.4 / <i>Burnt</i>	0.00	0.00	*20.34 F
12	9		*JOINT,FRAME BRAKE AIR LINE,NO.4 / <i>Burnt</i>	0.00	0.00	*140.04 F
13	6		*JOINT,BRAKE AIR LINE,NO.5 / <i>Burnt</i>	0.00	0.00	*418.92 F
14	1		*SWITCH,BRAKE AIR LINE PARKING / <i>Burnt</i>	0.00	0.00	*65.98 F
15	2		*JOINT,FRAME BRAKE AIR LINE,NO.4 / <i>Burnt</i>	0.00	0.00	*19.96 F
16	1		*CHAMBER ASSY ,FWD RR BRAKE,RH 24-24SPG (FP51SD) / <i>Burnt</i>	0.00	0.00	*460.00 F
17	1		*COVER A ; DUST / <i>Burnt</i>	0.00	0.00	*99.82 F
18	4		*SPRING,RR BRAKE SHOE RETURN / <i>Burnt</i>	0.00	0.00	*343.44 F
19	4		*SPRING,RR BRAKE SHOE RETURN / <i>Burnt</i>	0.00	0.00	*154.12 F
20	4		*SEAL,ACTUATOR / <i>Burnt</i>	0.00	0.00	*71.08 F
21	8		*PIN,RETURN SPG,RR / <i>Burnt</i>	0.00	0.00	*307.36 F
22	4		*CE RING / <i>Burnt</i>	0.00	0.00	*13.24 F
23	2		*COVER PLATE / <i>Burnt</i>	0.00	0.00	*23.86 F
24	2		*GROMMET / <i>nec</i>	0.00	0.00	*187.94 F
25	12		*BOLT,FR BRAKE / <i>nec</i>	0.00	0.00	*24.84 F
26	2		*OIL SEAL,RR WHEEL HUB,OTR / <i>Burnt</i>	0.00	0.00	*29.52 F
27	2		*BEARING,RR WHEEL HUB,OTR / <i>Burnt</i>	0.00	0.00	*397.50 F
28	2		*OIL SEAL,RR WHEEL HUB,INR (MOQ=2) / <i>Burnt</i>	0.00	0.00	*105.06 F
29	2		*BEARING,RR WHEEL HUB,INR / <i>Burnt</i>	0.00	0.00	*376.48 F
30	1		*BREATHER,RR AXLE HOUSING / <i>Burnt</i>	0.00	0.00	*16.58 F
31	2		*GASKET,RR AXLE SHAFT / <i>Burnt</i>	0.00	0.00	*8.38 F
32	1		*BUZZER,BACK / <i>Burnt</i>	0.00	0.00	*390.75 F
33	1		*HARNES,CHASSIS / <i>Burnt</i>	0.00	0.00	*11,629.56 F
34	1		*LAMP,COMBINATION,RR,RH / <i>Burnt</i>	0.00	0.00	*93.70 F
35	1		*LINING KIT,RR BRAKE / <i>Burnt</i>	0.00	0.00	*612.00 F
36	1		*TUBE ASSY,FRAME BRAKE AIR LINE / <i>Burnt</i>	0.00	0.00	*580.14 F
37	1		*TUBE ASSY,FRAME BRAKE AIR LINE / <i>Burnt</i>	0.00	0.00	*673.37 F
38	3		*TUBE,FWD RR AXLE BRAKE / <i>Burnt</i>	0.00	0.00	*138.18 F
39	1		*TUBE,FRAME BRAKE AIR LINE,NO.16 / <i>Burnt</i>	0.00	0.00	*183.74 F
40	1		*TUBE,FRAME BRAKE AIR LINE,NO.16 / <i>Burnt</i>	0.00	0.00	*202.76 F
41	1		*TUBE,FRAME BRAKE AIR LINE,NO.8 / <i>Burnt</i>	0.00	0.00	*156.06 F
42	1		*CLIP,RR BRAKE / <i>Burnt</i>	0.00	0.00	*105.44 F
43	1		*APRON, SPLASH	0.00	0.00	*87.24 F

F=Franchise part.

Total Parts (S\$) **28,770.54** ✓

Goldbell Engineering Pte Ltd/XE5826R/18/10/2022 11:31. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	CANVAS MOTOR WIRING	400.00
2	1	CHENGAL TIMBER AT CHASSIS	600.00
3	4	REAR RH TYRES	1,800.00
4	1	SIDE CANVAS (GREEN) LH & RH	800.00
5	1	SIDE MUDGUARD LH & RH	500.00
Sub Total (S\$)			4,100.00

Handwritten notes: Burnt, Burnt, Burnt, Burnt, 1600

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE AND REFIX BOTH SIDE MUDGUARD, BOTH SIDE CANVAS (GREEN), CANVAS MOTOR WIRING AND ALL CHENGAL TIMBER AT CHASSIS	New	1,500.00
2	TO PUTTY, CLEAN, SPRAY PAINT FOR REAR DECK	New	1,300.00
3	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC	New	4,500.00
4	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	New	800.00
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	New	800.00
Gross Labour Cost (S\$)			8,900.00

Handwritten notes: 1200, 900, 3000, 600, 700

Goldbell Engineering Pte Ltd/XE5826R/18/10/2022 11:31. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



AIRMAN.



38,970.54

supp - 15,216.15

54,186.69

Steve (LKK)
12/10/22, 4.00pm
OP - Not Authorise
Excess - ?
PIP
Resurvey Before spray
15 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: