

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010138/EVY3E2**Date:** 19/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SNW00006312201

**Claimant Vehicle
No :** GBD5549G**Insured Vehicle
No :** PD171D

Date of Loss: 05/10/2022

Nature of Claim: TP

Claim
No: SNM22D207130/C02/IRENE**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBD5549G**

Make & Model: RENAULT TRAFIC, 2.0 D (M)

Engine No: M9RA630C181790

Reg. Date: 10/12/2014 (Man. Year: 2014)

Chassis No: VF1FLB1B1EY782486

Colour: White

Odometer: 238454 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/65 R16

Rear Tyre Size: 225/65 R16

Front Left Side: Grenlander 4 mm

Rear Left Side: Grenlander 4 mm

Front Right Side: Grenlander 4 mm

Rear Right Side: Grenlander 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,046.00	21,126.60	12,919.40	37.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,680.00	10,880.00	4,800.00	30.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	49,726.00	32,006.60	17,719.40	35.63

INSPECTION

Date of Assignment: 18/10/2022

Date Inspected: 14/10/2022 Inspected At:

No. 2, Pesawat

Repairer: Wearnes automotive Pte Ltd (HQ)

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$20,000.00
OMV :	\$34,707.00
PARF Rebate (1) :	\$0
Quota Premium Paid :	\$49,901.00
COE Rebate (2) :	\$10,738.00
Total Rebate (1) + (2) = :	\$10,738.00

The total amount incurred will be Market Value \$20,000.00 minus Total Rebate \$10,738.00 = \$9,262.00

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 19 Oct 2022)	
Parts:	N/A	RENAULT TRAFIC 2.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBD5549G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PNL SIDE RHR LWB	Dented	1,320.60 FS	*1,320.60 FS
2	20		*ECROU A SERTIR M6X10	Necessary	170.00 FS	*170.00 FS
3	20		*CRIMPING NUT M8X125	Necessary	226.00 FS	*226.00 FS
4	1		*PILLAR RHR EXT	Dented	1,178.70 FS	*1,178.70 FS
5	1		*TRIM-RR RH END PLR	Not Necessary	841.90 FS	*- FS
6	1		*BRKT ASSY-STRUT MTG	Not Necessary	68.40 FS	*- FS
7	1		*DOUB BRAN G L2	Not Necessary	537.20 FS	*- FS
8	1		*LINING RRH	Dented	1,802.40 FS	*1,802.40 FS
9	10		*INSERT-RR BACK PLR E	Necessary	286.00 FS	*286.00 FS
10	1		*RENF AVD RAIL AR	Necessary	15.80 FS	*15.80 FS
11	1		*RENF CTR RAIL AR	Necessary	15.80 FS	*15.80 FS
12	1		*RENF ARD RAIL AR	Necessary	15.80 FS	*15.80 FS
13	1		*ROOF PANEL T	Dented	2,412.90 FS	*2,412.90 FS
14	1		*DRIP RAIL RR	Not Necessary	551.40 FS	*- FS
15	1		*MBR-CROSS, ROOF RR E	Not Necessary	221.40 FS	*- FS
16	1		*RAIDISSEUR PAVILL	Not Necessary	351.10 FS	*- FS
17	2		*SUPPORT RAIDISSEU	Not Necessary	146.00 FS	*- FS
18	1		*FLOOR-RR RR PART, L1	Not Necessary	384.80 FS	*- FS
19	1		*MBR ASSY-RR CROSS, O	Not Necessary	674.50 FS	*- FS
20	1		*APRON-RR	Dented	700.40 FS	*700.40 FS
21	1		*BUMPER PANEL REAR T2	Broken	803.00 FS	*803.00 FS
22	1		*WHEEL ARCH RHR	Crushed	999.70 FS	*999.70 FS
23	1		*BUMPER REAR RH T2	Not Necessary	363.60 FS	*- FS
24	1		*BUMPER REAR CTR T2	Not Necessary	430.30 FS	*- FS
25	2		*BUMPER REFLECTOR T2	Not Necessary	159.80 FS	*- FS
26	1		*TRIM-BACKLITE WIPER	Not Necessary	160.70 FS	*- FS
27	1		*TRIM DOOR	Not Necessary	104.20 FS	*- FS
28	1		*REAR LOGO RENAULT	Not Necessary	210.10 FS	*- FS
29	1		*REAR LOGO TRAFFIC	Necessary	195.70 FS	*195.70 FS
30	1		*PROTECT W/ARCH RR	Crushed	292.40 FS	*292.40 FS
31	1		*COVER W/ARCH	Crushed	292.40 FS	*292.40 FS
32	1		*GLAZED RRH DOOR	Dented	2,650.00 FS	*2,650.00 FS
33	1		*DOOR REAR LH	Not Necessary	2,235.80 FS	*- FS
34	2		*REAR DOOR HINGE RR R	Bent	572.80 FS	*572.80 FS
35	1		*BOX-STOP, TRUNK DOOR	Necessary	167.60 FS	*167.60 FS
36	1		*BOOT CHECK FLOH	Bent	143.40 FS	*143.40 FS
37	1		*RUNNER RH	Dented	234.80 FS	*234.80 FS
38	1		*RAIL-RH SLIDE DOOR	Dented	651.10 FS	*651.10 FS
39	1		*RAIL END COVER RH	Dented	58.90 FS	*58.90 FS
40	1		*RAIL-RH SLIDE DOOR, C	Dented	621.70 FS	*621.70 FS
41	1		*LOWER GUIDE RAIL OF	Not Necessary	476.00 FS	*- FS
42	1		*CHECK STRAP DOOR	Not Necessary	143.40 FS	*- FS
43	1		*HANDLE BRACKET	Not Necessary	209.90 FS	*- FS
44	1		*BOOT LOCK LOWER RH T	Not Necessary	242.90 FS	*- FS
45	1		*DOOR LOCK	Not Necessary	242.90 FS	*- FS
46	1		*BOOT DOOR LOCK CENTE	Not Necessary	483.30 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BOOT LOCK HANDLE FLO	Not Necessary	259.50 FS	*- FS
48	1		*JOINT ARRIE	Bent	241.60 FS	*241.60 FS
49	1		*BOOT SEAL CTR FLOH	Crushed	196.20 FS	*196.20 FS
50	1		*FOAM-ADHESIVE	Necessary	34.90 FS	*34.90 FS
51	1		*WINDSCREEN REAR RH T	Necessary	662.20 FS	*662.20 FS
52	1		*WINDSCREEN REAR LH T	Not Necessary	662.20 FS	*- FS
53	2		**D* PRIMER GLASS & P	Necessary	91.00 FS	*91.00 FS
54	4		*WINDSCREEN SEALANT	Necessary	536.00 FS	*536.00 FS
55	4		*ZV0890100070/NOISE D	Necessary	2,427.60 FS	*2,427.60 FS
56	1		*RALLONGE RADAR VU	Necessary	62.70 FS	*62.70 FS
57	1		*SET-PARKING AID	Not Necessary	679.80 FS	*- FS
58	3		*SEAM SEALANT	Necessary	147.00 FS	*147.00 FS
59	1		*HARN-RR ROOF	Not Necessary	1,071.70 FS	*- FS
60	1		*HARN-LWR LGT	Not Necessary	649.40 FS	*- FS
61	1		*BOOT LID WIRING - RHS	Not Necessary	155.30 FS	*- FS
62	1		*HARN-BODY, RR SPARE	Not Necessary	201.90 FS	*- FS
63	1		*RH RR CLSTR LIGHT	Broken	234.00 FS	*234.00 FS
64	1		*SUPT COMPL-RR RH LAM	Dented	478.90 FS	*478.90 FS
65	1		*REFLECTOR LAMP RH T2	Broken	186.60 FS	*186.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	34,046.00	21,126.60
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE RHR FENDER, RHR DOOR, REAR BUMPER, TAILLAMP, EMBLEMS, BRACKETS, CLIPS, ETC	New	3,850.00	2,750.00
2	TO REPLACE ROOF TOP PANEL	New	5,500.00	3,850.00
3	TO REPLACE RHR DOOR GLASS	New	550.00	550.00
4	TO INSTALL RHR DOOR GLASS SOLAR FILM	New	280.00	280.00
5	TO TRANSFER DOOR PARTS	New	500.00	500.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	450.00	450.00
7	TO BLEND AND SPRAY PAINT ON RHR FENDER, RHR DOOR, LHR DOOR, ROOF TOP PANEL, ETC	New	4,550.00	2,500.00
Gross Labour Cost (\$\$)			15,680.00	10,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >