



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 3630K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	BROKEN	1,342.10	1,342.10
1	FRONT BUMPER SIDE RETAINER RH	DAMAGED	41.00	41.00
2	FRONT BUMPER NOZZLE COVER @\$39.50	MISSING	79.00	79.00
1	FRONT BUMPER FOG LAMP GARNISH RH	DAMAGED	155.00	155.00
1	FRONT BUMPER EMBLEM 335I	NECESSARY	61.00	61.00
1	FRONT BUMPER INNER SIDE BRACKET RH	DAMAGED	154.70	154.70
1	FRONT FENDER SIGNAL LAMP GARNISH RH	NECESSARY	77.00	77.00
1	FRONT FENDER INNER SHIELD RH	TORN	166.00	166.00
1	FRONT FENDER AIR VENT RH	BROKEN	121.00	121.00
2	HEADLAMP @\$2014.78	O/S DEFACED / N/S BROKEN	4,029.56	4,029.56
2	HEADLAMP BRACKET @\$122.85	BROKEN	245.70	245.70
2	FRONT RADIATOR GRILLE @\$288.40	BROKEN	576.80	576.80
1	BONNET	TO REPAIR SEE LABOUR	1,457.80	-
	LESS 5% DISCOUNT		-425.33	-352.44
			8,081.33	6,696.42
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	55.00	55.00
1	FRONT BUMPER LOWER LIP (SN)	BROKEN	1,240.00	800.00
1	SET FRONT RADIATOR CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT FENDER RH (SN)	BROKEN	1,489.00	1,200.00
1	BONNET RACING STICKER (SN)	NECESSARY	480.00	250.00
1	FRONT TYRE RIM RH (SN)	SERVICEABLE	750.00	-
			4,044.00	2,335.00
<b><u>LABOUR</u></b>				
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS- MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF BONNET.		810.00	500.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL.		1,000.00	800.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		50.00	50.00
	SPECIALIST CHARGES - CHECK / DIAGNOSTIC AND REPROGRAMMING.	NOT NECESSARY	200.00	-
	SPECIALIST CHARGES - WHEEL ALIGNMENT.	NOT NECESSARY	60.00	-
	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY).		45.00	30.00
			2,165.00	1,380.00
<b>GRAND TOTAL</b>			<b>14,290.33</b>	<b>10,411.42</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,300.00</b>

Report Ref No. CS3/CT122000889/Gvy3e2-1

**XING GUO QIANG**

**M.MATAI, AMSAE-A**

**Automotive Assessor**

**ANG BRYAN TANI**

**Automotive Assessor / Investigator**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.