

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH8393X

11.10.2022

MAKE REG.29.06.2018

CHIANG/INCOME

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER <i>ll</i>		\$459.40
1	REAR BUMPER SIDE BRACKET LH/RH <i>X NN</i>		\$55.80
1	REAR BUMPER CENTRE MOULDING <i>ll</i>		\$451.25
2	REAR BUMPER REINFORCEMENT STAY LH/RH <i>?</i>		\$138.10
1	REAR BUMPER REINFORCEMENT <i>?</i>		\$394.80
1	REAR BUMPER FOG LAMP <i>?</i>		\$201.50
1	SMART KEY SENSOR <i>?</i>		\$40.50
1	REAR BUMPER NUMBER LAMP LH/RH <i>?</i>		\$85.30
1	TOWING COVER <i>X NN</i>		\$98.80
10	REAR BUMPER CLIPS <i>ll</i>		\$2.20
	SUB TOTAL		\$2,141.35
	20.00%		\$428.27
	DISCOUNTED TOTAL		\$1,713.08
1	REAR NUMBER PLATE W/HOLDER <i>BT</i>		\$55.00
1	REAR REVERSE SENSOR <i>X NN</i>		\$180.00
			\$211.50
	Labour Charge		
	Panel Beating		\$550.00
	Spray Painting Charge		\$300.00
	Tuff Kote		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$970.00
	ESTIMATE TOTAL		\$2,894.58
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

2 Days
4/5
6ms Ag
12/10
2pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey but not spray painting
- To display a sign, indicating resurvey
- Parts replaced are not for insurance
- Third party liability on "no prejudice" basis
- No claim for depreciation
- On the basis of the surveyor's report and is subject to the insurance company

Acknowledged

Signature

Date