



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8956Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER COVER	BROKEN	459.40	459.40
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER CENTRE MOULDING	CUT	451.25	451.25
1	REAR BUMPER REFLECTOR LAMP LH	SERVICEABLE	41.45	-
1	TAIL LAMP LH	SERVICEABLE	935.40	-
1	ASSY BLIND SPOT RADAR LH	NOT NECESSARY	1,784.40	-
1	REAR FENDER LH	TO REPAIR SEE LABOUR	1,768.30	-
1	REAR BUMPER SIDE BRACKET LH	BENT	55.80	55.80
	LESS 20% DISCOUNT		-1,103.60	-197.69
			4,414.40	790.76
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR FENDER PETROL STICKER (SN)	NECESSARY	15.00	15.00
			65.00	65.00
<u>LABOUR</u>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,050.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		60.00	30.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX UPHOLSTERY AND CUSHION RR.		120.00	60.00
			1,890.00	1,290.00
GRAND TOTAL			6,369.40	2,145.76

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			1,700.00
---	--	--	-----------------

Report Ref No. NS/INC22010147/Gqcm4



XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.