

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH8956Y

Make : HYUNDAI

Model : IONIQ

Date: 10/12/22

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER / <i>dc</i>			\$ 459.40	
10	REAR BUMPER CLIPS / <i>dc</i>			\$ 22.00	
1	REAR BUMPER CENTRE MOULDING / <i>cut</i>			\$ 451.25	
1	REAR BUMPER REFLECTOR LAMP LH ?			\$ 41.45	
1	TAIL LAMP LH ?			\$ 935.40	
1	ASSY BLIND SPOT RADAR LH <i>X NN</i>			\$ 1,784.40	
1	REAR FENDER LH <i>X Repair</i>			\$ 1,768.30	
1	REAR BUMPER SIDE BRACKET LH / <i>BT</i>			\$ 55.80	
SUB TOTAL				\$ 5,518.00	
LESS 20%				\$ 1,103.60	
DISCOUNTED TOTAL				\$ 4,414.40	
1	REAR BUMPER RUBBER MAT / <i>gmc</i>			\$ 50.00	Nett
1	REAR FENDER PETROL STICKER / <i>gmc</i>			\$ 15.00	Nett
				\$ 65.00	
Labour Charge					
PANEL BEATING				\$ 1,050.00	
SPRAY PAINTING CHARGE				\$ 600.00	
CHECK ALL LIGHTING				\$ 60.00	
TUFF KOTE				\$ 60.00	
REMOVE/ REFIX UPSHOLSTERY AND CUSHION RR				\$ 120.00	
TOTAL LABOUR				\$ 1,890.00	
ESTIMATE TOTAL				\$ 6,369.40	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

4 Days.

4/5

Garcia

12/10

3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair spray painting
- To display a sign during resurvey
- Participate in the resurvey
- Third party involvement
- No illegal activities on "prejudice" basis
- Signatures of the repairer and the insurance company

Acknowledged by:

Signature:

Date: