

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 4895M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TO REPAIR SEE LABOUR	571.85	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	371.75	-
	LESS 25% DISCOUNT		-235.90	-
			707.70	-
	NETT ITEMS			
10	REAR BUMPER CLIPS @\$4.00 (N)	NOT NECESSARY	40.00	-
	LESS 10% DISCOUNT		-4.00	-
			36.00	-
	SPECIAL NETT ITEMS			
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	180.00	-
			180.00	-
	<u>LABOUR</u>			
	TO KNOCK ,WELD ,REMOVE & FIX ON ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		500.00	200.00
	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS .		500.00	200.00
	TO CHECK WIRING.	NOT NECESSARY	30.00	-
	TO APPLY ANTI RUST COATING.	NOT NECESSARY	50.00	-
			1,080.00	400.00
	GRAND TOTAL		2,003.70	400.00

RECOMMENDED COST OF REPAIRS		400.00

Report Ref No. CS/FCI22010149/Rqy3q2

MARKET VALUE: \$40,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$19,638.00=NETT VALUE: \$20,362.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

1000

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.