

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010157/KQY3Q2**Date:** 24/11/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00033192203

Claimant Vehicle No : SLL2846H**Insured Vehicle No :** SJN1581R

Date of Loss: 09/10/2022

Nature of Claim: TP

Claim No: SNM22D207303/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLL2846H**

Make & Model: MAZDA 5, 2.0 SP.6EAT SUNROOF (A)

Engine No: PE10407566

Reg. Date: 20/02/2017 (Man. Year: 2016)

Chassis No: JM6CW1071G0124836

Colour: Metallic Grey

Odometer: 149621 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,871.64	3,167.24	6,704.40	67.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,000.00	1,330.00	1,670.00	55.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,871.64	4,497.24	8,374.40	65.06
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	12,871.64	3,500.00	9,371.64	72.81
+ GST 7.00/7.00% (S\$)	901.01	245.00	656.01	72.81
Nett Amount (S\$)	13,772.65	3,745.00	10,027.65	72.81

INSPECTION

Date of Assignment: 12/10/2022

Date Inspected: 13/10/2022 Inspected At:

Thiam Heng Huat Pte Ltd (SIN MING)
176 SIN MING DRIVE, #05-14
Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Nov 2022)	
Parts:	N/A	MAZDA 5 2.0 SP.6EAT SUNROOF (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL2846H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,892.30 FL	*1,637.00 FL
2	1		*TAILGATE MAZDA LOGO	Necessary	89.00 FL	*48.60 FL
3	1		*TAILGATE MAZDA 5 EMBLEM	Necessary	82.00 FL	*42.00 FL
4	1		*TAILGATE SKYACTIV EMBLEM	Necessary	93.00 FL	*60.00 FL
5	1		*TAILGATE WINDSCREEN MOULDING	Necessary	180.00 FL	*180.00 FL
6	1		*TAILGATE LOCK	Repair	250.70 FL	*- FL
7	1		*TAILGATE OUTER MOULDING	Serviceable	374.00 FL	*- FL
8	1		*TAILGATE INNER TRIM	Serviceable	561.60 FL	*- FL
9	1		*TAILGATE LAMP N/S	Cracked	499.40 FL	*356.00 FL
10	2		*TAILGATE LICENCE PLATE LAMP	Serviceable	379.40 FL	*- FL
11	1		*TAILLAMP N/S	Serviceable	689.40 FL	*- FL
12	1		*TAILLAMP INNER SEAL N/S	Serviceable	40.00 FL	*- FL
13	1		*REAR BUMPER	Buckled	1,163.40 FL	*961.20 FL
14	2		*REAR BUMPER SIDE RETAINER	Serviceable	233.60 FL	*- FL
15	2		*REAR BUMPER ATTACHMENT RETAINER	Serviceable	120.00 FL	*- FL
16	1		*REAR BUMPER REFLECTOR N/S	Cracked	152.90 FL	*120.00 FL
17	2		*REAR BUMPER SIDE SPONGE	Serviceable	356.00 FL	*- FL
18	2		*REAR BUMPER TOW COVER	Serviceable	96.00 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Repair	482.00 FL	*- FL
20	1		*END PANEL	Repair	981.40 FL	*- FL
21	1		*END PANEL TOP TRIM	Serviceable	387.70 FL	*- FL
22	1		*END PANEL BOTTOM TRIM	Serviceable	179.00 FL	*- FL
23	1		*EXHAUST ASSY	Repair	1,193.00 FL	*- FL
24	2		*EXHAUST ASSY STOPPER	Serviceable	64.00 FL	*- FL
25	1		*EXHAUST ASSY HEATSHIELD	Repair	163.00 FL	*- FL
26	1		*EXHAUST ASSY CHROME TIP	Dented	198.00 FL	*198.00 FL
27	10		*TAILGATE INNER TRIM CLIPS	Not Necessary	45.00 FS	*- FS
28	6		*TAILLAMP CLIPS	Not Necessary	27.00 FS	*- FS
29	10		*REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
30	6		*END PANEL TOP TRIM CLIPS	Not Necessary	27.00 FS	*- FS
31	6		*END PANEL BOTTOM TRIM CLIPS	Not Necessary	27.00 FS	*- FS
32	1		*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
33	1		*REVERSE SENSOR	Dented / Shorted	280.00 FS	*200.00 FS
34	1		*REVERSE CAMERA	Serviceable	450.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
36	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,051.80	3,887.80
- List Item Discount on L Items 20.00/20.00% (\$)	2,180.16	720.56
Total Parts (\$)	9,871.64	3,167.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEAT ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	500.00
2	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK FUNCTIONS INCLUDING TAILLAMP LIGHTINGS	New	50.00	20.00
3	TO REMOVE ,REFIT TAILGATE COMPONENTS TO REPLACE TAILGATE ,CHECK AND RE-ADJUST CLOSE GAP ,ALIGNMENT AND WATER SEEPAGE	New	100.00	60.00
4	TO REMOVE AND REFIT REAR WINDSCREEN TO FACILITATE REPAIR WORK	New	150.00	120.00
5	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL	New	1,200.00	600.00
6	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR	New	100.00	30.00
Gross Labour Cost (\$\$)			3,000.00	1,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >