

ASS. REC. BY:

REF:

072 / 22 00157 / kg

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

1 / Est not ready

31/10 11:00 @ 3500d Caber Used @ 9371.64, 737.7)

Veh No:

SLC 284614

Yr Regn:

02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda

c.c

1998

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

149821

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN8CW10716 0124836

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

d

mm

Rear

R/Bal.

d

mm

L/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

9/10/22

D.O.I.

13/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1) 23/11/2022

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format :

MER-TP

Lump Sum / I.B.I. (\$

3500

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: MAZDA 5

Engine/Chassis No.: JM6CW1071G0124836

Date of accident:

Damaged area: N/S Rear

Date: 14/10/2022

Claim Type: TP


VRN: SLL2846H

Not Authorized

11 hrs @ 3500/hr

Recovery After Paint

5 days



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tailgate 1637	1	\$ 1,892.30	\$ 1,892.30	✓
2	Tailgate "MAZDA" logo 48.60	1	\$ 89.00	\$ 89.00	✓
3	Tailgate "MAZDA 5" emblem 42	1	\$ 82.00	\$ 82.00	✓
4	Tailgate "SKYACTIV" emblem 60	1	\$ 93.00	\$ 93.00	✓
5	Tailgate windscreen moulding	1	\$ 180.00	\$ 180.00	✓
6	Tailgate lock	1	\$ 250.70	\$ 250.70	X
7	Tailgate outer moulding	1	\$ 374.00	\$ 374.00	X
8	Tailgate inner trim	1	\$ 561.60	\$ 561.60	X
9	Tailgate lamp n/s 336	1	\$ 499.40	\$ 499.40	✓
10	Tailgate licence plate lamp	2	\$ 189.70	\$ 379.40	X
11	Taillamp n/s	1	\$ 689.40	\$ 689.40	X
12	Taillamp inner seal n/s	1	\$ 40.00	\$ 40.00	X
13	Rear bumper 961.20	1	\$ 1,163.40	\$ 1,163.40	✓
14	Rear bumper side retainer	2	\$ 116.80	\$ 233.60	X
15	Rear bumper attachment retainer	2	\$ 60.00	\$ 120.00	X
16	Rear bumper reflector n/s 120	1	\$ 152.90	\$ 152.90	✓
17	Rear bumper side sponge	2	\$ 178.00	\$ 356.00	X
18	Rear bumper tow cover	2	\$ 48.00	\$ 96.00	X
19	Rear bumper reinforcement	1	\$ 482.00	\$ 482.00	X
20	End panel	1	\$ 981.40	\$ 981.40	X
21	End panel top trim	1	\$ 387.70	\$ 387.70	X
22	End panel bottom trim	1	\$ 179.00	\$ 179.00	X
23	Exhaust assy	1	\$ 1,193.00	\$ 1,193.00	X
24	Exhaust assy stopper	2	\$ 32.00	\$ 64.00	X
25	Exhaust assy heatshield	1	\$ 163.00	\$ 163.00	X
26	Exhaust assy chrome tip	1	\$ 198.00	\$ 198.00	✓
Subtotal				\$ 10,900.80	
List discount				20.00%	
Total				\$ 8,720.64	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Tailgate inner trim clips <i>nn</i>	10	\$ 4.50	\$ 45.00
2	Taillamp clips <i>nn</i>	6	\$ 4.50	\$ 27.00
3	Rear bumper clips <i>nn</i>	10	\$ 4.50	\$ 45.00
4	End panel top trim clips <i>nn</i>	6	\$ 4.50	\$ 27.00
5	End panel bottom trim clips <i>nn</i>	6	\$ 4.50	\$ 27.00
6	End panel sealant <i>nn</i>	1	\$ 100.00	\$ 100.00
7	Reverse sensor <i>nd / shot</i>	1	\$ 280.00	\$ 280.00
8	Reverse camera <i>sn</i>	1	\$ 450.00	\$ 450.00
9	Rear windscreen sealant <i>nn</i>	1	\$ 100.00	\$ 100.00
10	Sundries <i>nn</i>	1	\$ 50.00	\$ 50.00
Total				\$ 1,151.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew the accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ 150.00
5	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
Total labour			\$ 3,000.00

Estimate Grand Total	\$ 12,871.64
----------------------	--------------

LKK Auto Consultants hereby notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
Signature: _____
Date: _____