

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010159/EQY3E2**Date:** 10/04/2023**REFERENCE**

Insured/Claimant: RAFIQ CHEONG Policy No: DMPCSNA00151862202

Date of Loss: 04/09/2022 Nature of Claim: OD Claim No: SNM22D206303/C01/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFJ96A**
 Make & Model: PEUGEOT 3008, 1.6 (A) Engine No: 10FJCC2449873
 Reg. Date: 16/07/2018 (Man. Year: 2018) Chassis No: VF3M45GZWJS222567
 Colour: Grey Odometer: 33877 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: S\$77,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
 Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
 Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,436.70	14,123.10	21,313.60	60.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,830.00	12,100.00	2,730.00	18.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	50,266.70	26,223.10	24,043.60	47.83
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	49,766.70	25,723.10	24,043.60	48.31
+ GST 8.00/8.00% (S\$)	3,981.34	2,057.85	1,923.49	48.31
Nett Amount (S\$)	53,748.04	27,780.95	25,967.09	48.31

INSPECTION

Date of Assignment: 12/10/2022

Date Inspected: 14/10/2022 Inspected At: AutoFrance (HQ)
305 Alexandra Road, #02-01
Singapore 159942

Estimated Period of Repair: 19.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Apr 2023)
Parts:	144	PEUGEOT 3008 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFJ96A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
2	1		*FRONT BUMPER	Broken	1,179.00 FS	*1,179.00 FS
3	1		*GRILLE STRENGTH	Not Necessary	131.40 FS	*- FS
4	1		*GUARD GRILLE	Not Necessary	306.00 FS	*- FS
5	1		*SET FINISHER BUMPER	Broken	319.50 FS	*319.50 FS
6	1		*BUMPER MOULDING CENTRAL - BLACK	Cut	99.00 FS	*99.00 FS
7	1		*GUARD GRILLE	Cut	388.80 FS	*388.80 FS
8	1		*FINISHER SET-FRT BPR FOG LAMP COVER	Missing	99.00 FS	*99.00 FS
9	1		*FRT BADGE	Not Necessary	81.00 FS	*- FS
10	1		*BRACKET SET-FRT SIDE BUMPER	Broken	86.40 FS	*86.40 FS
11	1		*FRONT BUMPER MOULDING <CHROME>	Not Necessary	310.50 FS	*- FS
12	1		*PLUG-FRT BUMPER LWR GRILLE	Not Necessary	72.00 FS	*- FS
13	1		*BUMPER BRACKET	Not Necessary	234.00 FS	*- FS
14	1		*BUMPR DEFLECTOR	Broken	226.80 FS	*226.80 FS
15	1		*CASING INTERCOOLER	Broken	72.00 FS	*72.00 FS
16	1		*AIR DUCT FRT BPR FRT PART	Broken	130.50 FS	*130.50 FS
17	1		*BUMPER ABSORBER/F	Not Necessary	298.80 FS	*- FS
18	1		*REINFORCEMENT REAR-FRT BUMPER	Not Necessary	522.00 FS	*- FS
19	1		*BUMPER ABSORBER	Not Necessary	112.50 FS	*- FS
20	1		*FINISHER BUMPER	Missing	94.50 FS	*94.50 FS
21	1		*FRONT PANEL AIR DEFLECTOR	Not Necessary	234.00 FS	*- FS
22	1		*FRONT FACE CROSSMEMBER	Not Necessary	184.50 FS	*- FS
23	1		*FRONT WING RH ASSY	Dented	522.90 FS	*522.90 FS
24	1		*RHF FRONT WING INNER FRAME	Not Necessary	504.00 FS	*- FS
25	1		*MUDGUARD RH FRT	Crushed	144.00 FS	*144.00 FS
26	1		*SEAL - RH FRT WING	Not Necessary	90.00 FS	*- FS
27	1		*WING MOULDING RH <CHROME>	Missing	99.00 FS	*99.00 FS
28	1		*FRONT WING MOULDING RH	Broken	205.20 FS	*205.20 FS
29	1		*ENGINE BONNET ASSY	Dented	1,811.70 FS	*1,811.70 FS
30	1		*BONNET HINGE LH	Not Necessary	171.00 FS	*- FS
31	1		*BONNET HINGE RH	Not Necessary	171.00 FS	*- FS
32	1		*BONNET SOUND PROOFING	Torn	253.80 FS	*253.80 FS
33	1		*BONNET LOCK	Not Necessary	27.00 FS	*- FS
34	1		*HOOD HOOK	Not Necessary	54.00 FS	*- FS
35	4		*BUFFER - STOPPER BONNET	Not Necessary	90.00 FS	*- FS
36	1		*FRONT CANT RAIL RH PREPARE	Not Necessary	441.00 FS	*- FS
37	1		*BRACKET RHF BUMPER SUPPORT	Not Necessary	144.00 FS	*- FS
38	1		*REAR BUMPER	Not Necessary	881.10 FS	*- FS
39	1		*RR CENTRAL STRIP <CHROME>	Not Necessary	238.50 FS	*- FS
40	1		*OVERRIDE - RH REAR BUMPER	Not Necessary	248.40 FS	*- FS
41	1		*RECESS DOOR - REAR BUMPER (TOW HOOK)	Not Necessary	54.00 FS	*- FS
42	1		*REAR WING RH ASSY	Repair	1,872.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*MUDGUARD-RHR INNER FENDER	Not Necessary	252.00 FS	*- FS
44	1		*RR QUARTR GLASS RH	Not Necessary	252.00 FS	*- FS
45	1		*ENTRY SEAL AV	Not Necessary	154.80 FS	*- FS
46	1		*WEATHERSTRIP-REAR DOOR (@ BODY)	Not Necessary	171.00 FS	*- FS
47	1		*WING MOULDING RHR	Cut	207.00 FS	*207.00 FS
48	1		*FRONT DOOR RH ASSY	Dented	1,652.40 FS	*1,652.40 FS
49	1		*HINGE - UPPER RHR DOOR	Not Necessary	72.00 FS	*- FS
50	1		*HINGE - LOWER RH FRT / RH REAR DOOR	Not Necessary	72.00 FS	*- FS
51	1		*FRT DOOR STOP	Necessary	81.00 FS	*81.00 FS
52	1		*SEALING PANEL RHF DOOR	Necessary	112.50 FS	*112.50 FS
53	1		*RHF DOOR PROTECTOR	Cut	238.50 FS	*238.50 FS
54	1		*MOULDING RHF DOOR OUTER C PILLER	Necessary	85.50 FS	*85.50 FS
55	1		*MOULDING DRIP RH	Cut	36.00 FS	*36.00 FS
56	1		*FRT DOOR GLASS RH	Broken	225.00 FS	*225.00 FS
57	1		*WINDOW LIFTER RH	Not Necessary	514.80 FS	*- FS
58	1		*WINDOW CHANNEL RHF	Cut	220.50 FS	*220.50 FS
59	1		*GUIDE - RHF SLIDING DOOR	Not Necessary	63.00 FS	*- FS
60	1		*GUIDE - RHF DOOR	Not Necessary	63.00 FS	*- FS
61	1		*SEAL, WINDOW OUTSIDE RHF	Bent	90.00 FS	*90.00 FS
62	1		*SEAL - INNER RHF DOOR WINDOW	Cut	50.40 FS	*50.40 FS
63	1		*FRT DOOR LOCK RH	Not Necessary	261.00 FS	*- FS
64	1		*DOOR HANDLE RH, W/O CHROME	Not Necessary	261.00 FS	*- FS
65	1		*HANDLE HOLDER RH EXT	Broken	109.80 FS	*109.80 FS
66	1		*DOOR PANEL LINING RHF	Not Necessary	1,980.00 FS	*- FS
67	1		*TRIM - RHF DOOR WINDOW SWITCH	Not Necessary	243.00 FS	*- FS
68	1		*RHR DOOR ASSY	Repair	1,350.00 FS	*- FS
69	1		*SEALED PANEL RH	Not Necessary	112.50 FS	*- FS
70	1		*RHR DOOR PROTECTOR	Not Necessary	226.80 FS	*- FS
71	1		*FINISHER - RHR FRONT	Not Necessary	90.00 FS	*- FS
72	1		*MOULDING RHR	Not Necessary	117.00 FS	*- FS
73	1		*ALLOY WHEEL 17 CHICAGO (2PCS)	Cut (1Pc Only)	1,170.00 FS	*585.00 FS
74	1		*RADIATOR ASSY	Not Necessary	607.50 FS	*- FS
75	1		*MOTR-DRIVN FAN	Not Necessary	414.00 FS	*- FS
76	1		*FAN CONTROL	Not Necessary	93.60 FS	*- FS
77	1		*DEGASSING TANK	Broken	85.50 FS	*85.50 FS
78	1		*RADIATOR	Not Necessary	16.20 FS	*- FS
79	1		*INTERCOOLER ASSY	Bent	720.00 FS	*720.00 FS
80	1		*BRACKT-LH TOP INTERCOOLER	Broken	36.00 FS	*36.00 FS
81	1		*BRACKT-LH LOWER INTERCOOLER	Broken	36.00 FS	*36.00 FS
82	1		*BRACKT-RH LOWER INTERCOOLER	Broken	36.00 FS	*36.00 FS
83	1		*AIR HOSE - UPPER INTERCOOLER	Not Necessary	126.00 FS	*- FS
84	1		*AIR UNION	Not Necessary	126.00 FS	*- FS
85	1		*BARE HEADLAMP RH	Broken	954.00 FS	*954.00 FS
86	1		*MODULE - RH HEADLAMP REPAIR KIT	Broken	492.30 FS	*492.30 FS
87	1		*FOG HEADLIGHT - (USING BULB H11) (2PCS)	Broken (1Pc Only)	216.00 FS	*108.00 FS
88	1		*ELECT STRG MCSM <VIN>	Not Necessary	2,817.00 FS	*- FS
89	2		*ROD KIT, TIE	Not Necessary	180.00 FS	*- FS
90	2		*STEERING GAITER KIT	Not Necessary	198.00 FS	*- FS
91	1		*BALLJOINT KIT RH	Not Necessary	115.20 FS	*- FS
92	1		*FRT SWIVEL PIN RH	Not Necessary	630.00 FS	*- FS
93	1		*WISHBONE FRONT RH	Not Necessary	373.50 FS	*- FS
94	1		*FRT ARM BALL-JOINT	Not Necessary	99.00 FS	*- FS
95	1		*FRONT SUSPENSION REST CLIP	Not Necessary	45.00 FS	*- FS
96	1		*FRT SUSP.CUP	Not Necessary	9.00 FS	*- FS
97	1		*FRT SHOCK-ABSORBER TOP MTG	Not Necessary	81.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*FT SHOCK-ABSORB	Not Necessary	184.50 FS	*- FS
99	1		*DUST COVER - FRT SHOCK ABSORBER	Not Necessary	10.80 FS	*- FS
100	1		*F/ANTI-ROLL BAR	Not Necessary	325.80 FS	*- FS
101	2		*BAR LINK	Not Necessary	126.00 FS	*- FS
102	1		*EXT VIEW MIRROR RH	Broken	531.00 FS	*531.00 FS
103	1		*RR VIEW MIRROR RH	Broken	58.50 FS	*58.50 FS
104	1		*MIRROR CAPPING RH	Cut	58.50 FS	*58.50 FS
105	1		*SIDE FLASH-UNIT RH	Not Necessary	135.00 FS	*- FS
106	1		*SET FINISHER BUMPER	Broken	135.00 FS	*135.00 FS
107	1		*WASHER RESERVOIR	Crushed	153.00 FS	*153.00 FS
108	1		*FILLER PIPE WITH CAP	Missing	36.00 FS	*36.00 FS
109	1		*COWL RIGHT SIDE (AIR INTAKE GRILLE RH)	Broken	112.50 FS	*112.50 FS
110	2		*COOLANT	Not Necessary	36.00 FS	*- FS
111	4		*GLASS WEDGE	Necessary	3.60 FS	*3.60 FS
112	1		*WINDSCREEN GLASS	Broken	922.50 FS	*922.50 FS
113	1		*RH GLASS MOULDING	Cut	94.50 FS	*94.50 FS
114	1		*LH GLASS MOULDING	Necessary	94.50 FS	*94.50 FS
115	1		*FACE CROSSMEMBER	Not Necessary	72.90 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	35,436.70	14,123.10
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE REAR BUMPER	New	600.00	0.00
2	TO REMOVE AND REPLACE REAR RIGHT FENDER PANEL. (CUT)	New	1,200.00	900.00
3	TO REMOVE AND REPLACE REAR RIGHT QUARTER GLASS AND CONDUCT WATER LEAK TEST	New	600.00	0.00
4	TO REMOVE AND REPLACE REAR RIGHT AND FRONT RIGHT DOOR	New	1,200.00	900.00
5	TO REMOVE AND REPLACE FRONT RIGHT FENDER, BONNET AND FRONT BUMPER	New	1,800.00	1,800.00
6	TO RE-CONNECT ALL FRONT PORTION OF ACCIDENT AREA WITH HEADLAMP ADJUSTMENT FOR PROPER FOCUS	New	600.00	600.00
7	TO REMOVE AND REPLACE FRONT RADIATOR, A/C CONDENSER WITH TOP UP OF NEW AC GAS AND COOLANT	New	600.00	600.00
8	TO REMOVE AND REPLACE ALLOY WHEEL WITH BALANCING	New	120.00	60.00
9	TO REMOVE AND REPLACE POWER STEERING RACK COMPONENTS WITH SUSPENSION ITEMS	New	900.00	900.00
10	TO SUPPLY AND INSTALL FRONT RIGHT AND REAR RIGHT QUARTER PANEL 3M WINDOW FILM	New	350.00	200.00
11	ACCIDENT TOWING TO VANTAGE	New	140.00	140.00
12	TO CONDUCT BODY CAVITY PRESERVATIONS	New	240.00	240.00
13	TO VACUUM ALL GLASS SHATTERED DEBRIS FROM FRONT RIGHT DOOR	New	80.00	80.00
14	TO SPRAY PAINT FRONT BUMPER, BONNET, FRONT RIGHT FENDER, FRONT RIGHT DOOR, REAR RIGHT DOOR, REAR RIGHT FENDER, FRONT RIGHT MIRROR COVER	New	3,900.00	3,700.00
15	TO REMOVE AND REPLACE FRONT RIGHT MIRROR WITH COVER AND TRANSFER ALL COMPONENTS FROM OLD DOORS TO NEW	New	600.00	80.00
16	TO CONDUCT ECU RE-PROGRAMMING AND CLEAR OF FAULT CODES TO ENSURE PROPER FUNCTION	New	600.00	600.00
17	TO CONDUCT 4-WHEEL ALIGNMENT	New	350.00	350.00
18	TO REMOVE AND INSTALL FRONT WINDSCREEN GLASS WITH WATER LEAK TEST	New	600.00	600.00
19	TO SUPPLY AND INSTALL 3M SOLAR FILM FOR FRONT WINDSCREEN GLASS	New	350.00	350.00
Gross Labour Cost (\$\$)			14,830.00	12,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >