

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010160/RQY3E2**Date:** 18/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00014302100

**Claimant Vehicle
No :** SNC5216E**Insured Vehicle
No :** SLJ1873X

Date of Loss: 05/10/2022

Nature of Claim: TP

Claim
No: SNM22D207135/C02/TANCHCDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC5216E**

Make & Model: BMW X1, 1.8 SDRIVE 18L (A)

Engine No: 41196545B38A15F

Reg. Date: 27/10/2021 (Man. Year: 2021)

Chassis No: WBA32AA0X05U27326

Colour: Black

Odometer: 21168 km

Engine Capacity: 1499 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,495.65	3,630.60	1,865.05	33.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,782.00	5,273.00	1,509.00	22.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,277.65	8,903.60	3,374.05	27.48
+ GST 7.00/7.00% (S\$)	859.44	623.25	236.19	27.48
Nett Amount (S\$)	13,137.09	9,526.85	3,610.24	27.48

INSPECTION

Date of Assignment: 13/10/2022

Date Inspected: 29/11/2022 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2023)
Parts:	M1-SUV	BMW X1 1.8 SDRIVE 18L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC5216E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*BOOTLID	Bent	1,298.95 FS	*1,298.95 FS
3	1		*REAR BUMPER TRIM PANEL (X LINE)	Deformed	231.70 FS	*231.70 FS
4	1		*REAR LH BUMPER MOUNT	Not Necessary	166.90 FS	*- FS
5	1		*REAR RH BUMPER MOUNT	Not Necessary	166.90 FS	*- FS
6	1		*MOUNTING SMART OPENER	Necessary	47.00 FS	*47.00 FS
7	1		*REAR TRIM UNDERRIDE PROTECTION (X L	Scratched	151.10 FS	*151.10 FS
8	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	147.50 FS	*- FS
9	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	147.50 FS	*- FS
10	1		*REAR BUMPER PANEL PRIMED	Deformed	926.75 FS	*926.75 FS
11	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	272.45 FS	*272.45 FS
12	1		*REAR WINDOW (ESG)	Not Necessary	815.55 FS	*- FS
13	1		*SET ADHESIVE PADS FOR ACE 2.0	Necessary	37.35 FS	*37.35 FS
14	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
15	2		*(DG/SL) WINDSCREEN SEALANT (2 X KLE	Not Necessary	350.70 FS	*- FS
16	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML	Necessary	27.85 FS	*27.85 FS
17	5		*BLIND RIVET NUT M6	Necessary	13.50 FS	*13.50 FS
18	1		*EXPANDING NUT	Necessary	1.00 FS	*1.00 FS
19	1		*EXPANDING NUT	Necessary	1.00 FS	*1.00 FS
20	2		*EMBLEM GROMMET	Necessary	1.90 FS	*1.90 FS
21	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	72.85 FS	*72.85 FS
22	1		*LETTERING S DRIVE 18I	Necessary	98.35 FS	*98.35 FS
23	1		*LETTERING X1	Necessary	65.60 FS	*65.60 FS
24	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
25	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **5,495.65** **3,630.60**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BOOTLID, REAR BUMPER INCLUDING ATTACHMENTS CAUSED BY ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BOOTLID AND REAR BUMPER	New	2,076.00	1,972.00
3	TO REMOVE AND REPLACE REAR WINDSCREEN GLASS TO FACILITATE REPAIR	New	574.00	574.00
4	TO CARRY OUT BODY CAVITY PRESERVATION REAR BOOTLID	New	118.00	112.00
5	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
6	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
7	TO SUPPLY REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
8	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
9	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NE WBOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	504.00	504.00
Gross Labour Cost (\$\$)			6,782.00	5,273.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >