



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFU 1228Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	DISTORTED	958.10	958.10
1	REAR BUMPER SIDE RETAINER (N/S)	BENT	59.20	59.20
1	REAR BUMPER DIFFUSER	NOT NECESSARY	458.20	-
1	REAR BUMPER CENTRE RETAINER	NOT NECESSARY	170.40	-
1	REAR BUMPER LOWER LID	NOT NECESSARY	573.10	-
1	SET REAR BUMPER CLIP	NECESSARY	50.00	50.00
1	TAIL LAMP	NOT NECESSARY	308.10	-
1	TAIL LAMP LOWER REATINER	NOT NECESSARY	39.60	-
1	SET TAIL LAMP CLIP	NOT NECESSARY	20.00	-
1	REAR FENDER (N/S)	DENTED / BENT	1,299.10	1,299.10
1	REAR FENDER SIDE SHIELD	NOT NECESSARY	198.70	-
1	SET REAR FENDER SIDE SHIELD CLIP	NOT NECESSARY	50.00	-
1	REAR FENDER INNER TRIM	NOT NECESSARY	374.90	-
1	SET REAR FENDER INNER TRIM CLIP	NOT NECESSARY	50.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	290.20	-
1	REAR WHEEL BEARING	NOT NECESSARY	330.10	-
1	REAR BEARING HUB	NOT NECESSARY	178.70	-
1	REAR AXEL	NOT NECESSARY	1,458.10	-
	LESS 10% DISCOUNT		-686.65	-236.64
			6,179.85	2,129.76
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR SPORT RIM (N/S) (S/N)	DENTED	600.00	600.00
1	REAR TYRE (N/S) (S/N)	SERVICEABLE	400.00	-
			1,000.00	600.00
<b><u>LABOUR</u></b>				
	LABOUR TO CUT, WELD, PANEL BEAT AND STRAIGHTEN ALL ACCIDENT DAMAGE AREAS.		1,000.00	600.00
	LABOUR TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS.		1,000.00	500.00
	SPRAY ANTI RUST ON ACCIDENT AFFECTED PANEL.		100.00	30.00

Report Ref No. CS/FCI22010165/Uvy3m4



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK WIRING SYSTEM.		50.00	20.00
	CONDUCT WHEEL ALIGNMENT TEST.		150.00	60.00
	REMOVE, RENEW AND REFIT REAR UNDER CARRIAGE.	NOT NECESSARY	600.00	-
	REMOVE AND REFIT REAR REVERSE SENSOR.		50.00	50.00
	REMOVE AND REFIT REAR UPHOLSTER.		300.00	80.00
	REDO SEALANT ON GAP.	NOT NECESSARY	100.00	-
	REMOVE, RENEW AND REFIT REAR RIMS FOR BALANCING.	NOT NECESSARY	50.00	-
	REMOVE, RENEW AND REFIT REAR TYRE.	NOT NECESSARY	50.00	-
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	50.00	-
	DIGNOSTIC & RESET FAULT CODE.	NOT NECESSARY	300.00	-
			3,800.00	1,340.00
<b>GRAND TOTAL</b>			<b>10,979.85</b>	<b>4,069.76</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,200.00</b>
---------------------------------------------------------------------------------	--	--	-----------------

Report Ref No. CS/FCI22010165/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.