

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/GRB22003250/DQY3E2-1**Date:** 22/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : GBB1037D **Insured Vehicle No :** SLV2021T
 Date of Loss: 07/04/2022 Nature of Claim: TP Claim No: MFL2022D0001713

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBB1037D**
 Make & Model: MITSUBISHI FB70BB1SRDEA, 3.0 D (M) Engine No: 4M42A57918
 Reg. Date: 02/07/2008 (Man. Year: 2008) Chassis No: FB70BBA10498
 Colour: White Odometer: 914267 km
 Engine Capacity: 2977 cc
 Market Value/New Car Price: N/A
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: TRANSITO 5 mm Rear Left Side: TRANSITO 5 mm
 Front Right Side: TRANSITO 5 mm Rear Right Side: TRANSITO 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,531.46	4,291.25	13,240.21	75.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,341.00	2,190.00	1,151.00	34.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,872.46	6,481.25	14,391.21	68.95
Approved Total (Overridden) (\$\$)		5,200.00		
(\$\$)	20,872.46	5,200.00	15,672.46	75.09
+ GST 7.00/7.00% (\$\$)	1,461.07	364.00	1,097.07	75.09
Nett Amount (\$\$)	22,333.53	5,564.00	16,769.53	75.09

INSPECTION

Date of Assignment: 11/10/2022
 Date Inspected: 08/04/2022 Inspected At: Garage 13 Pte Ltd (HQ)
 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
 Singapore 415875
 Estimated Period of Repair: 7.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 22 Nov 2022)	
Parts:	N/A	MITSUBISHI FB70BB1SRDEA 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB1037D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	975.00 FL	*821.50 FL
2	1		*HEADLAMP LH	Holder Broken	784.00 FL	*635.20 FL
3	1		*SIGNAL LAMP LH	Defaced / Holder Broken	295.50 FL	*227.63 FL
4	1		*SIDE LAMP LH	Defaced / Holder Broken	232.80 FL	*184.12 FL
5	1		*FRONT DOOR LH	Crushed	2,350.00 FL	*1,498.00 FL
6	1		*FRONT DOOR GLASS OUTER MOULDING LH	Necessary	142.62 FL	*142.62 FL
7	2		*FRONT DOOR HINGE	Not Necessary	208.40 FL	*- FL
8	1		*FRONT DOOR CHECK LH	Not Necessary	125.00 FL	*- FL
9	1		*FRONT DOOR LOCK LH	Not Necessary	311.80 FL	*- FL
10	1		*FRONT DOOR STEP GARNISH LH	Grazed / Deformed	226.80 FL	*226.80 FL
11	1		*FRONT DOOR STEP PANEL LH	Distorted	385.60 FL	*298.60 FL
12	1		*FRONT DOOR WHEEL ARCH GARNISH LH	Deformed	210.50 FL	*175.30 FL
13	1		*FRONT DOOR INNER BOARD LH	Not Necessary	512.40 FL	*- FL
14	1		*FRONT DOOR INNER GARNISH LH	Not Necessary	125.80 FL	*- FL
15	1		*FRONT DOOR INNER HANDLE LH	Not Necessary	115.00 FL	*- FL
16	1		*FRONT DOOR OUTER HANDLE LH	Not Necessary	162.00 FL	*- FL
17	1		*FRONT DOOR GLASS REGULATOR MOTOR LH	Not Necessary	481.95 FL	*- FL
18	1		*FRONT DOOR GLASS REGULATOR LH	Not Necessary	411.65 FL	*- FL
19	1		*FRONT CABIN STEP BAR LH	Bent	128.00 FL	*128.00 FL
20	1		*FRONT CABIN REAR PILLAR LH	Repair	594.20 FL	*- FL
21	1		*FRONT CABIN LIFTING RACK	Not Necessary	325.80 FL	*- FL
22	1		*FUSE BOX	Not Necessary	228.00 FL	*- FL
23	1		*FRONT FENDER WHEEL SPLASH SHIELD LH	Deformed	265.10 FL	*172.13 FL
24	1		*FRONT WINDSCREEN DOOR PILLAR LH	Repair	609.93 FL	*- FL
25	1		*FRONT TIE ROD END LH	Not Necessary	209.00 FL	*- FL
26	1		*FRONT KNUCKLE ARM LH	Not Necessary	2,565.00 FL	*- FL
27	1		*FRONT KNUCKLE HUB AND BEARING LH	Not Necessary	202.00 FL	*- FL
28	1		*FRONT SHOCK ABSORBER LH	Not Necessary	280.00 FL	*- FL
29	1		*FRONT UPPER ARM LH	Not Necessary	853.00 FL	*- FL
30	1		*FRONT LOWER ARM LH	Not Necessary	3,558.00 FL	*- FL
31	1		*REAR CARRIAGE SIDE GATE LH	Repair	2,560.00 FL	*- FL
32	4		*REAR CARRIAGE SIDE GATE HINGES LH	Serviceable	180.80 FL	*- FL
33	1		*REAR CARRIAGE SIDE STEP LH	Repair	115.00 FL	*- FL
34	1		*REAR CARRIAGE SIDE GATE LATCH LH	Serviceable	126.20 FL	*- FL
35	1		*REAR WHEEL SPLASH SHIELD LH	Deformed	265.10 FL	*265.10 FL
36	1		*FRONT DOOR COMPANY STICKER LH	Necessary	60.00 FS	*60.00 FS
37	1		*SET FRONT DOOR INNER BOARD CLIPS	Not Necessary	40.00 FS	*- FS
38	1		*FRONT DOOR SEALANT LH	Not Necessary	40.00 FS	*- FS
39	1		*FRONT TYRE LH	Not Necessary	300.00 FS	*- FS
40	1		*FRONT RIM LH	Serviceable	450.00 FS	*- FS
41	1		*REAR CARRIAGE SIDE GATE COMPANY STICKER LH	Grazed / Necessary	350.00 FS	*350.00 FS
42	1		*REAR CARRIAGE WOODEN STORAGE BOX LH	Cut / Cracked	450.00 FS	*300.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (S\$)	22,811.95	5,485.00
				- List Item Discount on L Items 25.00/25.00% (S\$)	5,280.49	1,193.75
				Total Parts (S\$)	17,531.46	4,291.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	1,440.00	1,200.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	1,400.00	800.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	90.00	40.00
4	TRANSFER OF EXISTING FRONT DOOR MECHANISM TO NEW DOOR LH	New	90.00	60.00
5	WIRING AND BULB CHECKING	New	36.00	30.00
6	REMOVE AND REPLACE FRONT UNDERCARRIAGE WORK LH	New	225.00	0.00
7	SPECIALIST CHARGES - WHEEL ALIGNMENT	New	60.00	60.00
Gross Labour Cost (S\$)			3,341.00	2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >