

WDD2054402F465953.

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56

SINGAPORE 417883

TEL : 96273323 FAX 68442641

CO.REG NO. : 53049097-L

TPAXA.

Xiao Chan.

KARTHIKEVASHAN S/O GOVINDAN

8 Keng Chin Road #12-15

SINGAPORE 258710

DATE : 28/12/2022

ACCIDENT DATE : 02/10/2022

MODEL : MERCEDES BENZ / C180 CONVERTIBLE (R17 LED)

CHASSIS NO. : WDD2054402F465953

ESTIMATE COST OF REPAIRS TO MERCEDES BENZ CAR NO. : SNC3985G

1 PC FRONT BONNET <i>Dented.</i>	S \$ 2,480.00 NETT	2250-
2 PC FRONT HEADLAMP <i>cracked.</i>	\$ 6,600.00 NETT	6450
1 PC L/H FENDER <i>Not nec</i>	\$ 952.00 NETT <i>x</i>	
1 PC FRONT CENTRE HEADLAMP SUPPORT RETAINER <i>Not nec</i>	\$ 312.00 NETT <i>x</i>	
1 PC FRONT L/H HEADLAMP LOWER BRACKET <i>Not nec</i>	\$ 76.00 NETT <i>x</i>	
1 PC FRONT GRILLE <i>cracked</i>	\$ 798.00 NETT <i>✓</i>	
6 PC FRONT GRILLE CLIP <i>Not nec</i>	\$ 30.00 NETT <i>✓</i>	
1 PC FRONT GRILLE EMBLEM <i>Not nec</i>	\$ 298.00 NETT <i>✓</i>	
1 PC FRONT GRILLE INNER BASE GARNISH <i>cracked.</i>	\$ 412.00 NETT <i>✓</i>	
1 PC FRONT BUMPER <i>Deformed</i>	\$ 1,690.00 NETT <i>✓</i>	
2 PC FRONT BUMPER SIDE RETAINER <i>Not nec</i>	\$ 76.00 NETT <i>x</i>	
8 PC FRONT BUMPER CLIP <i>Not nec</i>	\$ 60.00 NETT <i>30.</i>	
2 PC FRONT BUMPER L/H SIDE PARKING SENSOR <i>1 piece damaged</i>	\$ 624.00 NETT <i>285.</i>	
1 PC FRONT BUMPER CENTRE GRILLE <i>Deformed.</i>	\$ 302.00 NETT <i>182.</i>	
1 PC FRONT BUMPER LOWER CHROME GARNISH <i>Not nec</i>	\$ 698.00 NETT <i>x</i>	
1 PC FRONT BUMPER TOP SUPPORT GARNISH <i>cracked.</i>	\$ 212.00 NETT <i>✓</i>	
1 PC FRONT BUMPER REINFORCEMENT BEAM <i>Not nec</i>	\$ 726.00 NETT <i>x</i>	
1 PC FRONT BUMPER SPONGE <i>cracked</i>	\$ 218.00 NETT <i>✓</i>	
1 PC FRONT NO. PLATE GARNISH <i>Deformed</i>	\$ 156.00 NETT <i>✓</i>	
1 PC FRONT NO. PLATE <i>Not nec</i>	\$ 26.00 S/NETT <i>x</i>	
1 PC FRONT NO. PLATE COVER <i>Not nec</i>	\$ 26.00 S/NETT <i>x</i>	

12839.

11555-10

LABOUR CHARGE

TO SPRAY PAINTING

\$ ~~650.00~~ 500

TO CHECK WIRING

\$ ~~50.00~~ 30.

TO REMOVE & REINSTALL FRONT BUMPER PARKING SENSOR , POSITION
CHECK & TEST FOR FUNCTIONING ALL SENSOR

\$ ~~120.00~~ 80.

TO RESET FAULT CODE & CARRY OUT DIAGNOSTIC CHECK

\$ ~~180.00~~ X.

LABOUR CHARGE TO PANEL BEATING , WELDING , REMOVING
ALL DAMAGED PARTS & REPLACING OF THE NEW PARTS ETC.

\$ ~~480.00~~ 450.

TO APPLY UNDERCOATING ON THE REPAIRED & REPLACED
PANEL FOR RUST PROTECTION

\$ 80.00 X. 1060

TOTAL : SS \$ 18,332.00

LKK Auto Consultants hence notify
the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TK MOTOR WORKSHOP



total: 12615.10
h/s : 10.1K.
05 Days.

10.1K
05 Days.