

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTAIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120**Our File No:** CC3/AIG22010177/AWCE2**Date:** 01/03/2023REFERENCE

Insured/Claimant:	ALI MUSLIM POTIA	Policy No:	1900258717-02		
Date of Loss:	08/10/2022	Nature of Claim:	OD	Claim No:	8844711495SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW9803B	Engine No:	CZD886608
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZF31L1015542
Reg. Date:	30/12/2019 (Man. Year: 2019)	Odometer:	9788 km
Colour:	Green		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,561.00	8,260.00	11,301.00	57.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,032.00	3,852.00	2,180.00	36.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,593.00	12,112.00	13,481.00	52.67
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	24,793.00	11,312.00	13,481.00	54.37
+ GST 8.00/8.00% (S\$)	1,983.44	904.96	1,078.48	54.37
Nett Amount (S\$)	26,776.44	12,216.96	14,559.48	54.37

INSPECTION

Date of Assignment:	14/10/2022		
Date Inspected:	13/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** XinYu*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,235.00 FS	*987.60 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Not Necessary	66.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	242.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - LH	Cut	124.00 FS	*98.80 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	212.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Cut	426.00 FS	*340.80 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	171.00 FS	*136.40 FS
8	1		*RADIATOR GRILLE	Not Necessary	1,594.00 FS	*- FS
9	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	271.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	114.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	974.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Not Necessary	137.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - LH	Damaged	43.00 FS	*34.24 FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	9.00 FS	*- FS
15	1		*CAUTION SIGN STICKER	Not Necessary	16.00 FS	*- FS
16	1		*HORN HIGH TONE - LH	Not Necessary	154.00 FS	*- FS
17	1		*HORN BRACKET - LH	Not Necessary	25.00 FS	*- FS
18	1		*FRONT PARKING AID SENSOR	Not Necessary	266.00 FS	*- FS
19	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
20	1		*FRONT FENDER - LH	Dented	1,445.00 FS	*1,156.00 FS
21	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	66.00 FS	*- FS
22	1		*FRONT FENDER BRACE - LH	Bent	98.00 FS	*77.68 FS
23	1		*FRONT FENDER BRACKET - LH	Damaged	39.00 FS	*30.48 FS
24	1		*FRONT WHEEL HOUSING LINER - LH	Not Necessary	260.00 FS	*- FS
25	1		*FRONT WHEEL HOUSING LINER COVER - LH	Not Necessary	18.00 FS	*- FS
26	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	264.00 FS	*- FS
27	1		*HEADLIGHT - LH	Cracked	5,952.00 FS	*4,761.60 FS
28	1		*HEADLIGHT POWER MODULE	Not Necessary	850.00 FS	*- FS
29	1		*HEADLIGHT HEAT SINK	Not Necessary	870.00 FS	*- FS
30	1		*HEADLIGHT HOSE - LH	Not Necessary	28.00 FS	*- FS
31	1		*LIFT CYLINDER - LH	Damaged	231.00 FS	*184.40 FS
32	1		*LIFT CYLINDER HOSE	Not Necessary	92.00 FS	*- FS
33	1		*LIFT CYLINDER WASH WATER RESERVOIR	Not Necessary	240.00 FS	*- FS
34	1		*RADIATOR AIR GUIDE - LH	Not Necessary	43.00 FS	*- FS
35	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	96.00 FS	*- FS
36	2		*FRONT WHEEL COVER - LH / RH	Necessary	566.00 FS	*452.00 FS
37	1		*FRONT ALUMINIUM RIM	Not Necessary	1,750.00 FS	*- FS
38	1		*FRONT ALUMINIUM RIM RUBBER VALVE	Not Necessary	4.00 FS	*- FS
39	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
40	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 19,561.00 8,260.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND REINSTALL FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR	New	280.00	280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
5	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,650.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			6,032.00	3,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >