

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010178/AVCE2**Date:** 03/01/2023**REFERENCE**

Insured/Claimant:	FRANCIS GOH MUK HSIUNG	Policy No:	2100510066	
Date of Loss:	10/10/2022	Nature of Claim:	OD	Claim No: 9412538620SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP8088T		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK034006
Reg. Date:	12/06/2017 (Man. Year: 2017)	Chassis No:	WAUZZZF54HA032392
Colour:	Black	Odometer:	92929 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30 R20	Rear Tyre Size:	265/30 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	50,261.00	20,570.56	29,690.44	59.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,132.00	9,382.00	9,750.00	50.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	69,393.00	29,952.56	39,440.44	56.84
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	68,593.00	29,152.56	39,440.44	57.50
+ GST 7.00/7.00% (S\$)	4,801.51	2,040.68	2,760.83	57.50
Nett Amount (S\$)	73,394.51	31,193.24	42,201.27	57.50

INSPECTION

Date of Assignment:	14/10/2022		
Date Inspected:	13/10/2022	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	14.0 days		

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	425.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP - LH / RH	Not Necessary	79.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	254.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	144.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	2,576.00 FS	*2,060.80 FS
8	2		*FRONT PARKING AID SENSOR SUPPORT - LH / RH	Necessary	116.00 FS	*91.52 FS
9	1		*RADIATOR GRILLE COVER - UPPER	Smashed	209.00 FS	*166.80 FS
10	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	1,058.00 FS	*- FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	899.00 FS	*719.20 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	139.00 FS	*110.80 FS
13	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	82.00 FS	*- FS
14	1		*FRONT BUMPER BRACKET - LH / RH	O/S Bent	508.00 FS	*203.20 FS
15	1		*FRONT BUMPER TOP COVER	Deformed	143.00 FS	*114.00 FS
16	1		*CAUTION SIGN STICKER	Necessary	16.00 FS	*12.40 FS
17	1		*AIR CONDITIONER STICKER	Necessary	9.00 FS	*6.64 FS
18	1		*LOCK CARRIER	Bracket Cracked	154.00 FS	*122.80 FS
19	2		*FRONT BUMPER SUPPORT - LH / RH	Damaged	64.00 FS	*51.04 FS
20	1		*HORN HIGH TONE - LH	Not Necessary	134.00 FS	*- FS
21	1		*HORN LOW TONE - RH	Not Necessary	139.00 FS	*- FS
22	2		*HORN BRACKET - LH / RH	Not Necessary	66.00 FS	*- FS
23	2		*FRONT PARKING AID SENSOR - INNER	Not Necessary	531.00 FS	*- FS
24	4		*FRONT PARKING AID SEAL RING	Not Necessary	10.00 FS	*- FS
25	1		*SET FRONT BUMPER WIRING	Not Necessary	567.00 FS	*- FS
26	1		*FRONT FENDER - LH / RH	O/S Buckled	2,378.00 FS	*951.20 FS
27	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
28	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	166.00 FS	*- FS
29	2		*FRONT FENDER BRACKET - LH / RH	Not Necessary	82.00 FS	*- FS
30	11		*FRONT FENDER RIVET	Necessary	42.00 FS	*33.44 FS
31	2		*FRONT FENDER DEFORMATION ELEMENT BRACKET - LH / RH	Not Necessary	110.00 FS	*- FS
32	1		*FRONT FENDER TRIM - LH / RH	O/S Necessary	342.00 FS	*136.40 FS
33	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	598.00 FS	*- FS
34	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	164.00 FS	*- FS
35	2		*FRONT WHEEL SPOILER STONE CHIP GUARD - LH / RH	Not Necessary	114.00 FS	*- FS
36	1		*FRONT FENDER LEDGE COVER - LH / RH LONG	O/S Deformed	80.00 FS	*31.44 FS
37	1		*FRONT FENDER LEDGE COVER - LH / RH SHORT	O/S Deformed	36.00 FS	*13.92 FS
38	1		*BONNET	Distorted	3,491.00 FS	*2,792.80 FS
39	1		*BONNET ATTACHMENT PARTS	Not Necessary	128.00 FS	*- FS
40	2		*BONNET HINGE - LH / RH	Not Necessary	932.00 FS	*- FS
41	3		*BONNET IMPACT PROTECTION - CENTER / LH / RH	Necessary	93.00 FS	*73.20 FS
42	1		*BONNET ENGINE SOUND ABSORBER	Not Necessary	382.00 FS	*- FS
43	1		*BONNET STRIKER - LH / RH	O/S Bent	112.00 FS	*44.56 FS
44	2		*BONNET GAS FILLED STRUT - LH / RH	Not Necessary	256.00 FS	*- FS
45	1		*BONNET LOCK - LH / RH	O/S Damaged	455.00 FS	*182.00 FS
46	1		*BONNET BOWDEN CABLE - CENTER	Damaged	64.00 FS	*50.56 FS
47	1		*BONNET BOWDEN CABLE COVER	Not Necessary	11.00 FS	*- FS
48	1		*BONNET RELEASE CABLE - CENTER	Not Necessary	64.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
49	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS
50	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
51	1		*WINDSCREEN WIPER SCUTTLE PANEL	Not Necessary	108.00 FS	*- FS
52	1		*HEADLIGHT - LH / RH	O/S Cracked/N/S Not Necessary	16,832.00 FS	*6,732.80 FS
53	2		*HEADLIGHT COMPENSATING PIECE - LH / RH	Not Necessary	89.00 FS	*- FS
54	2		*HEADLIGHT COMPENSATING PIECE - LH / RH	Not Necessary	93.00 FS	*- FS
55	2		*HEADLIGHT COMPENSATING PIECE - LH / RH	Not Necessary	89.00 FS	*- FS
56	2		*LIFT CYLINDER - LH / RH	Not Necessary	434.00 FS	*- FS
57	1		*LIFT CYLINDER BRACKET - LH / RH	O/S Damaged	34.00 FS	*12.88 FS
58	1		*LIFT CYLINDER CORRUGATED PIPE	Necessary	100.00 FS	*79.44 FS
59	1		*LOCK CARRIER	Cracked	1,478.00 FS	*901.60 FS
60	2		*RADIATOR SUPPORT BRACKET - LH / RH	Cracked	85.00 FS	*67.68 FS
61	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
62	1		*A/C CONDENSER	Dented	683.00 FS	*546.00 FS
63	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	21.00 FS	*16.32 FS
64	1		*RADIATOR	Dented	1,013.00 FS	*810.40 FS
65	6		*READY-MIX COOLANT	Necessary	297.00 FS	*237.12 FS
66	1		*RADIATOR FAN RING	Not Necessary	292.00 FS	*- FS
67	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	2,489.00 FS	*- FS
68	1		*RADIATOR AIR GUIDE - LH / RH INNER	O/S Cracked	72.00 FS	*28.16 FS
69	2		*RADIATOR AIR GUIDE - LH / RH OUTER	Deformed	38.00 FS	*29.28 FS
70	1		*RADIATOR AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
71	1		*INTAKE AIR DUCT - RH	Not Necessary	25.00 FS	*- FS
72	1		*INTAKE HOSE ENGINE AIR	Cut	61.00 FS	*48.48 FS
73	1		*INTAKE HOSE	Not Necessary	110.00 FS	*- FS
74	1		*AIR FILTER	Not Necessary	418.00 FS	*- FS
75	1		*RADIATOR AIR GUIDE - UPPER	Not Necessary	19.00 FS	*- FS
76	2		*FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH	Not Necessary	892.00 FS	*- FS
77	1		*FRONT ROOF CHROME MOLDING - LH / RH	O/S Cut	1,412.00 FS	*564.80 FS
78	2		*FRONT WATER DEFLECTOR STRIP - LH / RH	Not Necessary	150.00 FS	*- FS
79	2		*FRONT DOOR CHROME TRIM - LH / RH	Necessary	342.00 FS	*272.80 FS
80	1		*FRONT NO PLATE	Necessary	120.00 FS	*120.00 FS
81	1		*SUNDRIES	Necessary	500.00 FS	*139.68 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 50,261.00 20,570.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,600.00	1,600.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR	New	560.00	560.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDER AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	8,000.00	3,000.00
6	TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, BONNET, HINGES BOTH FRONT DOORS AND BOTH UPPER A-PILLARS	New	7,500.00	3,300.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$)			19,132.00	9,382.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >