

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22010181/KVY3M4**Date:** 22/02/2023**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959853
Claimant Vehicle No :	SJB2398K	Insured Vehicle No :	SLH4173Z
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	287121

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB2398K	Engine No:	L15A5155664
Make & Model:	HONDA AIRWAVE, 1.5 M (A)	Chassis No:	GJ11204741
Reg. Date:	04/01/2008 (Man. Year: 2007)	Odometer:	261107 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,590.16	3,252.64	337.52	9.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,490.00	640.00	30.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,720.16	4,742.64	977.52	17.09

INSPECTION

Date of Assignment:	17/10/2022		
Date Inspected:	11/10/2022	Inspected At:	CARIS AUTOWORKS PTE LTD 160 SIN MING DRIVE, #05-03 SIN MING AUTOCITY, SINGAPORE 575722
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Feb 2023)
Parts: M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJB2398K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER (REAR)	Bent	1,178.30 FL	*1,178.30 FL
2	1		*BOOT	Bent	1,582.30 FL	*1,582.30 FL
3	1		*END PANEL (REAR)	Bent	558.20 FL	*558.20 FL
4	1		*SET PARKING SENSOR	Cracked	237.92 FS	*200.00 FS
5	1		*BOOT LOCK	Dented	152.80 FL	*152.80 FL
6	1		*BOOT PULL HANDLE	Serviceable	38.20 FL	*- FL
7	1		*END PANEL GARNISH	Dented	183.50 FL	*183.50 FL
8	1		*HONDA LOGO WITH CHROME	Serviceable	298.80 FL	*- FL
9	1		*AIRWAVE LOGO	Necessary	48.20 FL	*48.20 FL
10	1		*NUMBER PLATE	Cracked	50.00 FL	*50.00 FL
11	1		*BODY CLIPS	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,408.22	4,003.30
- List Item Discount on L Items 20.00/20.00% (S\$)	818.06	750.66
Total Parts (S\$)	3,590.16	3,252.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL KNOCKING	New	600.00	600.00
2	SPRAY PAINTING	New	1,000.00	750.00
3	WHEEL ALIGNMENT	New	100.00	0.00
4	WIRE CHECKING & DIAGNOSTIC	New	80.00	20.00
5	LABOUR CHARGE TO REMOVE WINDSCREEN TO INSTALL IN NEW BOOT	New	350.00	120.00
			Gross Labour Cost (\$\$)	2,130.00
				1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >