

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 7921D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	CRACKED	459.40	459.40
2	REAR BUMPER SIDE BRACKET LH/RH @\$55.80	NOT NECESSARY	111.60	-
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
2	REAR BUMPER REINFORCEMENT STAY LH/RH @\$138.10	NOT NECESSARY	276.20	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	394.80	-
1	REAR BUMPER LOWER CENTRE MOULDING	CUT	155.00	155.00
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	SMART KEY SENSOR	NOT NECESSARY	40.50	-
1	REAR BUMPER NUMBER PLATE LH/RH	NOT NECESSARY	85.30	-
1	TOWING COVER	NOT NECESSARY	98.80	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-459.27	-217.53
			1,837.08	870.12
	NETT ITEMS			
1	REAR NUMBER PLATE W/HOLDER (N)	MISSING	55.00	55.00
1	REAR REVERSE SENSOR (N)	NOT NECESSARY	180.00	-
	LESS 10% DISCOUNT		-23.50	-5.50
			211.50	49.50
	<u>LABOUR</u>			
	PANEL BEATING.		550.00	350.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	REMOVE/REFIX REVERSE SENSOR .		60.00	40.00
			970.00	640.00
	GRAND TOTAL		3,018.58	1,559.62





Page No.:2 of 2

RECOMMENDED COST OF REPAIRS		1,559.62
(CONFIRMED)		

Report Ref No. NS/INC22010182/Gncq2

XING GUO QIANG

Automotive Assessor

M.MATAI, AMSAE-A

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser