

(08/11/13) waf

ASS. REC. 5Y:

REF:

CS/LPC22010185/Rwy3

653m

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SBS 5023C

at Workshop m/s SBS TRANSIT

of AMK DEPOT w/p hp

Insured:

LPC

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No:

SBS 5023C

Yr Regn:

2010 / PCB

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SCANIA KUB4X29.2LA

C.C

9290

Colour

MULTI

A/C:

Insured / Std / NI / NA

Sp. Reading

103897

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

4S2K4X2001866857

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

2 - D/D

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

14/10/22

D.O.I.

14/10/22

Survey held at

AMK DEPOT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS SI

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

DATE: 13.10.2022

DAY : Thu

Workshop Accident Repair Estimate

FOR WORKSHOP ONLY

ACCIDENT DATE

11.10.2022

BUS REGISTRATION NUMBER

SBS5033C

SBS5033C

ACCIDENT TIME

09:32PM

BUS TYPE (DD OR SD)

DD

THIRD PARTY CLAIM AGAINST

Accident Reference & Bus No

AR-2022-2955

S/No	SECTION A :	PARTS & MATERIAL COST
	Part or Item Description	Quantity
1	HEADLAMP COVER O/S F/GLASS C (30122054) <i>W</i>	1
2	TOGGLE (30122016) <i>NA</i>	2
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
TOTAL PARTS & MATERIAL COST		\$ 254.00

S/No	SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)
1	contractor's repair charges -Auto Team	Quotation
2	Workshop Labour	
3	Spray Painting & Sikaflex x 255	
4	Vinyl	NA
5	Touch up sticker	Sticker & AVD
6	Towing	CRS Towing
TOTAL LABOUR COST		\$838

SECTION C :	SUMMARY
	TOTAL DOWNTIME-1 dar
	TOTAL REPAIR COSTS
	\$1,092

Name of Surveyor:

Company Name:

DATE Surveyor :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasm
Hp 90010068
1 days
7/P
14/10/22 @ 16w
Resy before paint