

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 132S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR RH	DENTED / GRAZED	12,700.00	5,217.00
1	REAR DOOR OUTSIDE HANDLE RH	SERVICEABLE	286.50	-
1	REAR DOOR WINDOW APERTURE SEAL RH	NECESSARY	257.00	257.00
1	REAR DOOR INNER SEAL RH	NECESSARY	220.00	220.00
1	REAR DOOR OUTER SEAL RH	NECESSARY	170.00	170.00
1	SET REAR DOOR TRIM PANEL CLIPS RH	NECESSARY	34.00	34.00
			13,667.50	5,898.00
	<u>LABOUR</u>			
	SPRAY PAINTING ON REAR DOOR / OUTSIDE HANDLE & REPAIRED PARTS INCLUDING SUPPLY OF PAINT MATERIALS.		900.00	300.00
	REMOVE DAMAGED PARTS, KNOCK OUT DENTS, REMOVE & REINSTALL NECESSARY FITTINGS TO FACILITATE, REPAIRS, RESHAPE, REFIT, ADJUST, REPLACE AND REALIGN ALL RELEVENT PARTS.		950.00	250.00
	TO CARRY OUT DIAGNOSTIC CHECKS & RESET.		580.00	180.00
	CHECK WIRING, RE-CONNECTION SOCKET, LIGHTING SYSTEM, POWER WINDOW & CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		120.00	20.00
	TO TRANSFER REAR DOOR MECHANISM & COMPONENTS.	NOT NECESSARY	120.00	-
	TO RE-WRAP REAR DOOR PAINT PROTECTION FILM.		480.00	250.00
	TO CAVITY PRESERVATION ON ALL AFFECTED AREAS.		100.00	30.00
			3,250.00	1,030.00
	GRAND TOTAL		16,917.50	6,928.00

RECOMMENDED COST OF LUMP SUM REPAIRS		5,550.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS3/LPC22007530/Kcy3e2-1

KONG SENG CHEONG

Licensed Appraiser