

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS3/III22003943/RVY3E2-1**Date:** 08/11/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MCV0001247\_01  
**Claimant Vehicle No :** SMY6408H **Insured Vehicle No :** PC9065Z  
 Date of Loss: 25/04/2022 Nature of Claim: TP Claim No: MCV2022D0002182

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY6408H**  
 Make & Model: MAZDA 3, 1.5 4DR M-HYBRID CLASSIC (A) Engine No: P520727784  
 Reg. Date: 18/03/2021 (Man. Year: 2021) Chassis No: JM6BP2SAAM1107151  
 Colour: White Odometer: 92153 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: RAPID 6 mm Rear Left Side: RAPID 6 mm  
 Front Right Side: RAPID 6 mm Rear Right Side: RAPID 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,794.96	2,402.08	3,392.88	58.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,391.00	1,660.00	731.00	30.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,185.96</b>	<b>4,062.08</b>	<b>4,123.88</b>	<b>50.38</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,250.00</b>		
<b>(\$\$)</b>	8,185.96	3,250.00	4,935.96	60.30
<b>+ GST 7.00/7.00% (\$\$)</b>	573.02	227.50	345.52	60.30
<b>Nett Amount (\$\$)</b>	<b>8,758.98</b>	<b>3,477.50</b>	<b>5,281.48</b>	<b>60.30</b>

INSPECTION

Date of Assignment: 11/10/2022  
 Date Inspected: 27/04/2022 Inspected At: Garage 13 Pte Ltd (HQ)  
 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46  
 Singapore 415875  
 Estimated Period of Repair: 5.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but*

*any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2022)
<b>Parts:</b>	143	MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMY6408H)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut / Snapped	1,097.20 FL	*997.40 FL
2	1		*REAR BUMPER SIDE RETAINER	N/S Cracked / O/S Refix	95.00 FL	*33.20 FL
3	1		*TAIL LAMP LH	Not Necessary	669.00 FL	*- FL
4	1		*REAR FENDER LH	Distorted	1,280.00 FL	*1,280.00 FL
5	1		*REAR FENDER INNER TRIM LH	Not Necessary	223.00 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	120.00 FL	*120.00 FL
7	1		*REAR FENDER INNER SPLASH SHIELD LH	Not Necessary	149.00 FL	*- FL
8	1		*REAR AIR VENT LH	Not Necessary	68.00 FL	*- FL
9	1		*REAR SHOCK ABSORBER LH	Not Necessary	498.00 FL	*- FL
10	1		*REAR WHEEL BEARING LH	Necessary	84.50 FL	*84.50 FL
11	1		*REAR DOOR LH	Repair	1,385.00 FL	*- FL
12	1		*REAR RIM LH	Dented / Warped	560.00 FS	*300.00 FS
13	1		*REAR TYRE LH	Not Necessary	280.00 FS	*- FS
14	1		*REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
15	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
16	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
17	1		*SET REAR FENDER INNER SHIELD CLIP LH	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>6,928.70</b>	<b>2,905.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	1,133.74	503.02
<b>Total Parts (S\$)</b>	<b>5,794.96</b>	<b>2,402.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	855.00	600.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	750.00	600.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	40.00	40.00
4	REMOVE AND REFIX UPHOLSTERY, CUSHION SEAT & REAR INNER TRIMS TO FACILITATE REPAIR	New	135.00	60.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS. (2-MAN JOB)	New	135.00	120.00
6	REMOVE AND REFIX FUEL TANK, PIPES TO FACILITATE THE REPAIR WORKS	New	67.50	60.00
7	SPECIALIST CHARGES - WHEEL ALIGNMENT	New	80.00	60.00
8	REMOVE AND REPLACE REAR UNDERCARRIAGE WORK LH	New	225.00	80.00
9	REMOVE AND REPLACE REAR REVERSE SENSOR	New	72.00	40.00
10	WIRING / BULB CHECKING (INCLUSIVE OF RE-FOCUS / RE-ADJUST ON ANGLE OF LIGHT INTENSITY)	New	31.50	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,391.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >