

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22010189/EYA3Q2**Date:** 17/07/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SLR8218A **Insured Vehicle No :** SML7624L
 Date of Loss: 10/10/2022 Nature of Claim: TP Claim No: MFL2022D0005704

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR8218A**
 Make & Model: HONDA SHUTTLE HYBRID, 1.5 (A) Engine No: LEB4266410
 Reg. Date: 29/08/2017 (Man. Year: 2016) Chassis No: GP71046138
 Colour: White Odometer: 245720 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
 Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm
 Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,931.76	2,436.76	495.00	16.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	1,680.00	1,280.00	43.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,891.76	4,116.76	1,775.00	30.13
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	5,891.76	3,200.00	2,691.76	45.69
+ GST 8.00/8.00% (S\$)	471.34	256.00	215.34	45.69
Nett Amount (S\$)	6,363.10	3,456.00	2,907.10	45.69
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,823.45		

INSPECTION

Date of Assignment: 14/10/2022
 Date Inspected: 14/10/2022 Inspected At: Lion City Rentals Pte Ltd (HQ)
 Estimated Period of Repair: 6.0 days No. 4 Jalan Besut S(619557)

Adjuster: CHEN TSUE YEE**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 May 2023)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8218A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented	920.10 FL	*920.10 FL
2	1		*REAR BOOT WEATHERSTRIP	Crushed	380.00 FL	*380.00 FL
3	1		*REAR BUMPER	Dented	860.80 FL	*860.80 FL
4	1		*REAR END PANEL TOP GARNISH	Crushed	146.30 FL	*146.30 FL
5	1		*REAR LH TAILLAMP REFLECTOR	Broken	345.00 FL	*345.00 FL
6	1		*SET BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
7	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
8	1		*SET END PANEL TOP GARNISH CLIPS	Necessary	80.00 FS	*15.00 FS
9	1		*SET BODY SEALANT	Necessary	300.00 FS	*30.00 FS
10	1		*SET WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,462.20	2,967.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	530.44	530.44
Total Parts (\$\$)	2,931.76	2,436.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO LABOUR CHARGE FOR REMOVING REAR TAILGATE ,REAR END PANEL,REAR BUMPER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGE PARTS	New	1,000.00	800.00
2	TO RESPRAY REAR TAILGATE ,REAR BUMPER ,END PANEL AND SPARE TYRE PANEL	New	900.00	600.00
3	TO CONDUCT A STANDARD OF OPERATING PROCEDURES POST REPAIR SCAN TEST AS A REQUIREMENT UPON COMPLETION OF COLLISION REPAIRS	New	300.00	0.00
4	TO REMOVE AND INSTALL REAR TAILGATE GLASS	New	180.00	120.00
5	TO DEACTIVATE AND ACTIVE HIGH VOLTAGE HYBRID BATTERY AS SAFETY PRECAUTIONS	New	300.00	100.00
6	TO APPLY RUSTPROOFING ON ALL DAMAGED PARTS	New	180.00	30.00
7	TO CHECK WIRING SYSTEM	New	100.00	30.00
Gross Labour Cost (S\$)			2,960.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >