

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010193/KPA3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7220048685
Claimant Vehicle No :	SNG8894G	Insured Vehicle No :	SFY6999B
Date of Loss:	11/10/2022	Nature of Claim:	TP
		Claim No:	8934416318SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNG8894G	Engine No:	2ZR2N37944
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU00J068324
Reg. Date:	12/09/2022 (Man. Year: 2021)	Odometer:	7216 km
Colour:	Metallic Grey		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,194.50	2,603.30	2,591.20	49.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,090.00	1,380.00	710.00	33.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,284.50	3,983.30	3,301.20	45.32
+ GST 7.00/7.00% (S\$)	509.92	278.83	231.09	45.32
Nett Amount (S\$)	7,794.42	4,262.13	3,532.29	45.32
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,664.13		

INSPECTION

Date of Assignment:	14/10/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	14/10/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK
Estimated Period of Repair:	4.0 days	Autopoint
		Singapore 568047

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,096.00 FL	*929.00 FL
2	1		*REAR TAILGATE PRIUS PLUS EMBLEM	Necessary	77.00 FL	*77.00 FL
3	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	68.00 FL	*68.00 FL
4	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	355.00 FL	*- FL
5	1		*REAR TAILGATE INNER LOCK	Repair	425.00 FL	*- FL
6	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	362.00 FL	*- FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	75.00 FL	*75.00 FL
8	1		*REAR BUMPER	Buckled	589.00 FL	*549.40 FL
9	1		*REAR BUMPER SIDE BRACKET LH	Cracked	144.00 FL	*144.00 FL
10	1		*REAR BUMPER SIDE BRACKET RH	Cracked	144.00 FL	*144.00 FL
11	1		*REAR BUMPER LOWER LIP	Dented	726.00 FL	*698.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	225.00 FL	*225.00 FL
13	1		*REAR END PANEL	Repair	696.00 FL	*- FL
14	1		*REAR END PANEL UPPER COVER	Mtg Cracked	175.00 FL	*175.00 FL
15	1		*REAR FLOOR PANEL TOOLBOX TRAY	Serviceable	427.00 FL	*- FL
16	1		*REAR FLOOR PANEL TOOLBOX UPPER BOARD	Serviceable	542.00 FL	*- FL
17	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
20	1		*REAR BUMPER REVERSE SENSOR	Dented	300.00 FS	*200.00 FS
21	1		*REAR END PANEL JOINT SEALANT	Not Necessary	80.00 FS	*- FS
22	1		*REAR END PANEL UPPER COVER CLIPS	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	6,726.00	3,374.40
- List Item Discount on L Items 25.00/25.00% (\$)	1,531.50	771.10
Total Parts (\$)	5,194.50	2,603.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST REAR ACCIDENT AREAS & ETC	New	700.00	500.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR BUMPER ,REAR END PANEL & ETC	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS ,REAR WINDSCREEN MOULDING ,REAR WINDSCREEN SEALANT & ETC	New	150.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC .BACK TO ORIGINAL OPERATIONS	New	120.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	50.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	120.00	30.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	100.00	0.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM	New	80.00	20.00
Gross Labour Cost (S\$)			2,090.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >