

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22010196/KPA3Q2**Date:** 26/04/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100496728
<b>Claimant Vehicle No :</b>	SMN4687P	<b>Insured Vehicle No :</b>	GBF6097B
Date of Loss:	13/10/2022	Nature of Claim:	TP
		Claim No:	1911186513SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMN4687P</b>	Engine No:	LEB6739325
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Chassis No:	RU31319310
Reg. Date:	13/08/2019 (Man. Year: 2018)	Odometer:	100797 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Farroad 9 mm	Rear Left Side:	Firenza 8 mm
Front Right Side:	Farroad 9 mm	Rear Right Side:	Dunlop 2 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,286.48	2,031.44	2,255.04	52.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,380.00	580.00	29.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,246.48</b>	<b>3,411.44</b>	<b>2,835.04</b>	<b>45.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,700.00</b>		
<b>(S\$)</b>	6,246.48	2,700.00	3,546.48	56.78
<b>+ GST 7.00/7.00% (S\$)</b>	437.25	189.00	248.25	56.78
<b>Nett Amount (S\$)</b>	<b>6,683.73</b>	<b>2,889.00</b>	<b>3,794.73</b>	<b>56.78</b>
<b>+ Loss of Use (5.0 x S\$60.00/day) (S\$)</b>		300.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,191.00</b>		

**INSPECTION**

Date of Assignment:	14/10/2022	Optima Werkz Pte Ltd (HQ)
Date Inspected:	14/10/2022 Inspected At:	10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Estimated Period of Repair:	4.0 days	Singapore 568047

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,068.10 FL	*953.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	138.60 FL	*138.60 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	52.50 FL	*- FL
4	1		*REAR TAILGATE VEZEL EMBLEM	Necessary	58.80 FL	*58.80 FL
5	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	57.90 FL	*57.90 FL
6	1		*REAR TAILGATE LAMP LH	Serviceable	480.80 FL	*- FL
7	1		*REAR TAILGATE OUTER CHROME MOULDING	Serviceable	112.50 FL	*- FL
8	1		*REAR TAILGATE MECHANISM LOCK	Dented	96.40 FL	*96.40 FL
9	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	155.20 FL	*- FL
10	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	105.20 FL	*- FL
11	1		*REAR TAIL LAMP LH	Serviceable	520.70 FL	*- FL
12	1		*REAR BUMPER	Buckled	858.60 FL	*762.00 FL
13	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	26.50 FL	*- FL
14	1		*REAR BUMPER REFLECTOR LH	Serviceable	178.50 FL	*- FL
15	1		*REAR BUMPER INNER BUZZER	Cracked	110.10 FL	*110.10 FL
16	1		*REAR END PANEL	Repair	484.10 FL	*- FL
17	1		*REAR END PANEL TOP GARNISH	Serviceable	103.60 FL	*- FL
18	1		*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
19	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
20	1		*REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
21	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
22	1		*REAR BUMPER REVERSE SENSOR	Scratched	300.00 FS	*200.00 FS
23	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
24	1		*REAR END PANEL JOINT SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,208.10</b>	<b>2,466.80</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	921.62	435.36
<b>Total Parts (\$\$)</b>	<b>4,286.48</b>	<b>2,031.44</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX ,REPAIR & READJUST ACCIDENT AREAS	New	700.00	500.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	700.00	600.00
3	LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
4	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & BACK TO ORIGINAL OPERATIONS	New	100.00	60.00
5	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR	New	100.00	50.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	80.00	30.00
7	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	80.00	0.00
8	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,960.00</b>	<b>1,380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >