

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22010198/Rqy3m4
	8 SHENTON WAY SINGAPORE 0688		Date:	02/11/2022	
	ATTN: LOW GARN		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 544Y	Veh. Inspected	t	GBK 8895A
	Policy No.	VFX/P2419140	Coverage (\$)		0.00
	Claim No.	S2M04CQV	Excess (\$)		0.00
	Assign From	LOW GARNET	Assign Date		13/10/2022
2. Vehicle Particulars & Condition					
	Make & Model	PEUGEOT PARTNER 1.5 BLUE	c.c		1499
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	VR3EFYHZRLJ738961	Colour		GREY
	Odometer	042422 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	FAIR			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	MICHELIN		6 mm
	L/H Front Tyre	205/60 R16	MICHELIN		6 mm
	R/H Rear Tyre	205/60 R16	MICHELIN		6 mm
	L/H Rear Tyre	205/60 R16	MICHELIN		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR N/S PORTION.				
5.	General Information				
	Accident Date	12/10/2022	Inspect Date /	Time	13/10/2022 (04:02 PM)
	Survey held at HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				

Report Ref No. CS3/ASM22010198/Rqy3m4

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$