

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010203/AYA3Q2**Date:** 17/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900009973
Claimant Vehicle No :	SGG4115G	Insured Vehicle No :	SMH7802K
Date of Loss:	07/10/2022	Nature of Claim:	TP
		Claim No:	3789495836SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGG4115G	Engine No:	L15C1001201
Make & Model:	HONDA CIVIC, 1.5 (A)	Chassis No:	FK71001204
Reg. Date:	19/12/2019 (Man. Year: 2018)	Odometer:	28045 km
Colour:	Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,539.92	8,946.32	8,593.60	48.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,430.00	3,360.00	4,070.00	54.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,969.92	12,306.32	12,663.60	50.72
Approved Total (Overridden) (S\$)		9,850.00		
Nett Amount (S\$)	24,969.92	9,850.00	15,119.92	60.55
+ Car Rental (10.0 x S\$100.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,857.45		

INSPECTION

Date of Assignment:	10/10/2022	HD Perfect Autowork Pte Ltd (HQ)
Date Inspected:	10/10/2022 Inspected At:	8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Estimated Period of Repair:	9.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR SIDE MIRROR LH	Not Necessary	979.20 FL	*- FL
2	1		*FRONT DOOR LH	Distorted	1,294.30 FL	*1,294.30 FL
3	1		*FRONT DOOR OUTER HANDLE LH	Cracked	277.60 FL	*277.60 FL
4	1		*FRONT DOOR KEY LOCK LH	Not Necessary	169.40 FL	*- FL
5	2		*FRONT DOOR STOPPER LH	Not Necessary	32.40 FL	*- FL
6	1		*FRONT DOOR TOP MOULDING LH	Not Necessary	134.60 FL	*- FL
7	2		*FRONT DOOR HINGE LH	Not Necessary	119.60 FL	*- FL
8	1		*FRONT DOOR SPEAKER LH	Cracked	196.30 FL	*196.30 FL
9	1		*FRONT DOOR INNER TRIM LH	Cracked	678.90 FL	*545.00 FL
10	1		*FRONT DOOR INNER LOCK LH	Damaged	329.80 FL	*329.80 FL
11	1		*FRONT DOOR LOCK CATCHER LH	Not Necessary	54.30 FL	*- FL
12	1		*FRONT DOOR WEATHERSTRIP LH	Cut	137.20 FL	*137.20 FL
13	1		*FRONT DOOR OUTER STRIP LH	Not Necessary	120.10 FL	*- FL
14	1		*FRONT DOOR LOWER INNER RUBBER LH	Not Necessary	59.60 FL	*- FL
15	1		*FRONT DOOR POWER WINDOW MOTOR C/W REGULATOR LH	Not Necessary	399.40 FL	*- FL
16	1		*FRONT DOOR GLASS CHANNEL LH	Not Necessary	79.40 FL	*- FL
17	1		*CENTER PILLAR (OUTER)LH	Dented	1,249.30 FL	*798.00 FL
18	1		*CENTER PILLAR (INNER)LH	Repair	1,089.70 FL	*- FL
19	1		*CENTER PILLAR INNER TRIM LH	Not Necessary	289.60 FL	*- FL
20	1		*ROCKER PANEL LH (OUTER)	Repair	429.80 FL	*- FL
21	1		*SIDE SKIRT LH	Cracked	510.00 FL	*510.00 FL
22	1		*SIDE SKIRT SPOILER LH	Cracked	486.20 FL	*486.20 FL
23	1		*REAR DOOR LH	Distorted	1,291.70 FL	*1,291.70 FL
24	1		*REAR DOOR WIRE HARNESS LH	Not Necessary	421.60 FL	*- FL
25	1		*REAR DOOR FRAME STEP GARNISH LH	Not Necessary	89.40 FL	*- FL
26	1		*REAR DOOR OUTER HANDLE LH	Damaged	269.50 FL	*269.50 FL
27	1		*REAR DOOR LOWER RUBBER LH	Not Necessary	55.70 FL	*- FL
28	2		*REAR DOOR HINGE LH	Bent	105.40 FL	*105.40 FL
29	1		*REAR DOOR CHECKER LH	Not Necessary	98.40 FL	*- FL
30	1		*REAR DOOR INNER LOCK LH	Damaged	234.60 FL	*234.60 FL
31	1		*REAR DOOR LOCK CATCHER LH	Not Necessary	25.40 FL	*- FL
32	1		*REAR DOOR INNER TRIM LH	Cracked	654.20 FL	*577.00 FL
33	1		*REAR DOOR WEATHERSTRIP LH	Cut	118.60 FL	*118.60 FL
34	1		*REAR DOOR POWER WINDOW MOTOR C/W REGULATOR LH	Damaged	341.70 FL	*341.70 FL
35	1		*REAR DOOR GLASS CHANNEL LH	Not Necessary	65.80 FL	*- FL
36	1		*REAR DOOR OUTER STRIP LH	Deformed	108.70 FL	*108.70 FL
37	1		*REAR DOOR FRAME WEATHERSTRIP LH	Not Necessary	155.80 FL	*- FL
38	1		*REAR FENDER LH	Repair	989.70 FL	*- FL
39	1		*REAR FENDER COWLING LH	Torn	172.20 FL	*172.20 FL
40	1		*REAR LOWER ARM LH	Bent	198.30 FL	*198.30 FL
41	1		*REAR UPPER ARM LH	Not Necessary	208.40 FL	*- FL
42	1		*REAR SWING ARM LH	Bent	289.40 FL	*289.40 FL
43	1		*REAR SHOCK ABSORBER LH	Necessary	321.50 FL	*321.50 FL
44	1		*REAR LINKAGE LH	Not Necessary	98.70 FL	*- FL
45	1		*REAR WHEEL HUP C/W BEARING LH	Damaged	389.60 FL	*389.60 FL
46	1		*REAR KNUCKLE ARM LH	Damaged	347.80 FL	*347.80 FL
47	1		*REAR ABS SENSOR LH	Not Necessary	298.80 FL	*- FL
48	1		*REAR BUMPER	Torn	1,294.30 FL	*855.00 FL
49	1		*REAR BUMPER SIDE DIFFUSER	Not Necessary	894.30 FL	*- FL
50	1		*REAR BUMPER SIDE RETAINER	Not Necessary	156.20 FL	*- FL
51	1		*CENTER PILLAR (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
52	1		*SET SIDE SKIRT CLIP	Necessary	80.00 FS	*30.00 FS
53	1		*REAR FENDER SEALANT LH	Necessary	150.00 FS	*60.00 FS
54	1		*REAR FENDER COWLING CLIP LH	Necessary	60.00 FS	*30.00 FS
55	1		*CENTER PILLAR STICKER	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*REAR FENDER SIDE GARNISH SEALANT LH	Not Necessary	80.00 FS	*- FS
57	1		*REAR FENDER GARNISH INNER SEAL LH	Not Necessary	60.00 FS	*- FS
58	1		*REAR WHEEL TYRE LH	Not Necessary	800.00 FS	*- FS
59	1		*REAR WHEEL RIM LH	Cut	850.00 FS	*550.00 FS
60	1		*SET WHEEL CAP	Not Necessary	120.00 FS	*- FS
61	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
62	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

				Sub Total (\$\$)	21,302.40	10,985.40
				- List Item Discount on L Items 20.00/20.00% (\$\$)	3,762.48	2,039.08
				Total Parts (\$\$)	17,539.92	8,946.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,800.00	1,300.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,300.00
3	WIRING CHECK	New	250.00	30.00
4	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	120.00
5	REMOVE AND REFIX SAFETY BELT	New	250.00	100.00
6	REMOVE AND REFIX FRONT DOOR WINDOW GLASS	New	120.00	40.00
7	TRANFER FRONT DOOR MECHANISM	New	80.00	40.00
8	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	220.00
9	FOUR WHEEL ALIGNMENT	New	120.00	80.00
10	REMOVE AND REFIX REAR DOOR WINDOW GLASS	New	120.00	40.00
11	TRANFER REAR DOOR MECHANISM	New	80.00	40.00
12	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
13	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
14	REMOVE AND REFIX REAR FENDER GARNISH LH	New	80.00	0.00
15	RESET ABS LIGHT	New	350.00	0.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/ CONTROL UNITS RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (S\$)			7,430.00	3,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >