

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLJ 729L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	UPPER ARM O/S	DISTORTED	1,008.00	1,008.00
1	LOWER ARM O/S	BENT	1,372.00	1,372.00
1	WHEEL CARRIER O/S	BENT	826.00	826.00
1	WHEEL HUB ASSY O/S	BENT	896.00	896.00
1	SHOCK ABSORBER O/S	BENT	2,660.00	2,660.00
1	FRONT FENDER O/S	CRACKED	5,040.00	5,040.00
	LESS 10% DISCOUNT		-1,180.20	-1,180.20
			10,621.80	10,621.80
1	FRONT ALLOY WHEEL O/S	DENTED	2,972.00	2,250.00
	LESS 10% DISCOUNT		-	-225.00
			2,972.00	2,025.00
	SPECIAL NETT ITEMS			
12	FRONT FENDER LINER O/S CLIPS @\$6.50 (SN)	NECESSARY	78.00	78.00
1	FRONT TYRE O/S (SN)	SERVICEABLE	780.00	-
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			908.00	78.00
	<u>LABOUR</u>			
	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEAT ,RESHAPE ,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.		1,400.00	800.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK FUNCTIONS.		100.00	20.00
	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY AFFECTED AREA /PANEL .		1,200.00	400.00
	TO RUST PROOF ALL AFFECTED PORTIONS AFTER REPAIR .	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT N/S FRONT UNDERCARRIAGE FOR REPLACEMENT OF PARTS.		800.00	280.00
	TO REMOVE AND REPLACE N/S FRONT TYRE & RIM .TO PERFORM TYRE BALANCING.		300.00	30.00

Report Ref No. CS/AGI22010207/Kvy3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT.		150.00	100.00
			4,050.00	1,630.00
	GRAND TOTAL		18,551.80	14,354.80

RECOMMENDED COST OF LUMP SUM REPAIRS		11,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI22010207/Kvy3q2

KONG SENG CHEONG

Licensed Appraiser