

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010208/AYA3Q2**Date:** 08/06/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000122
Claimant Vehicle No :	SNA8420Y	Insured Vehicle No :	YP3144T
Date of Loss:	09/10/2022	Nature of Claim:	TP
		Claim No:	1090934206SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA8420Y		
Make & Model:	MERCEDES-BENZ A180, 1.3 COMPT SALN PROGRESSIVE (R18 LED) (A)	Engine No:	28291480046097
Reg. Date:	17/05/2019 (Man. Year: 2018)	Chassis No:	WDD1770842J055116
Colour:	Grey	Odometer:	55657 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	47,985.30	26,193.80	21,791.50	45.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,120.00	2,920.00	8,200.00	73.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	59,105.30	29,113.80	29,991.50	50.74
Approved Total (Overridden) (S\$)		23,300.00		
Nett Amount (S\$)	59,105.30	23,300.00	35,805.30	60.58
+ Car Rental (11.0 x S\$120.00/day + 7.00% GST) (S\$)		1,412.40		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		24,839.85		
Global Sum Settlement (S\$)		24,500.00		

INSPECTION

Date of Assignment:	10/10/2022	
Date Inspected:	10/10/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,644.00 FL	*1,644.00 FL
2	1		*FRONT BUMPER LOGO	Necessary	123.00 FL	*123.00 FL
3	1		*FRONT BUMPER SENSOR RH	Not Necessary	238.00 FL	*- FL
4	4		*FRONT BUMPER SENSOR HOLDER	Not Necessary	260.00 FL	*- FL
5	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	302.00 FL	*- FL
6	1		*HEADLAMP RH	Cracked	3,861.00 FL	*3,861.00 FL
7	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	121.00 FL	*- FL
8	1		*BONNET	Dented	1,988.00 FL	*1,988.00 FL
9	1		*BONNET LOCK	Not Necessary	68.00 FL	*- FL
10	1		*BONNET LOCK CATCH	Not Necessary	178.00 FL	*- FL
11	2		*BONNET HINGE	Not Necessary	388.00 FL	*- FL
12	1		*FRONT WINDSCREEN MOULDING	Not Necessary	165.00 FL	*- FL
13	1		*FRONT WINDSCREEN SIDE MOULDING RH	Not Necessary	188.00 FL	*- FL
14	1		*FRONT FENDER RH	Distorted	879.00 FL	*879.00 FL
15	1		*FRONT FENDER INNER COWLING RH	Deformed	351.00 FL	*351.00 FL
16	1		*FRONT FENDER INNER GARNISH RH	Deformed	186.00 FL	*186.00 FL
17	1		*FRONT WHEEL HOUSE PANEL RH	Repair	6,300.00 FL	*- FL
18	1		*FRONT WHEEL HOUSE TOP PANEL RH	Repair	628.00 FL	*- FL
19	1		*SIDE SKIRT RH	Not Necessary	862.00 FL	*- FL
20	1		*FRONT WHEEL RIM RH	Cut	1,522.00 FL	*1,522.00 FL
21	1		*FRONT ABS SENSOR RH	Not Necessary	385.00 FL	*- FL
22	1		*FRONT CROSSMEMBER	Not Necessary	2,541.00 FL	*- FL
23	1		*FRONT STEERING RACK AND PINION	Bent	8,189.00 FL	*6,985.00 FL
24	1		*FRONT KNUCKLE ARM RH	Damaged	1,530.00 FL	*1,255.00 FL
25	1		*FRONT WHEEL HUP WITH BEARING RH	Damaged	650.00 FL	*550.00 FL
26	1		*FRONT SHOCK ABSORBER RH	Not Necessary	983.00 FL	*- FL
27	1		*FRONT LOWER ARM RH	Damaged	990.00 FL	*715.00 FL
28	2		*FRONT LOWER ARM BUSH RH	Damaged	570.00 FL	*155.00 FL
29	1		*FRONT STABILIZER LINKAGE RH	Not Necessary	141.00 FL	*- FL
30	1		*FRONT DOOR SIDE MIRROR RH	Missing	2,385.00 FL	*1,458.00 FL
31	1		*FRONT DOOR RH	Distorted	2,584.00 FL	*2,180.00 FL
32	1		*FRONT DOOR TOP CHROME MOULDING RH	Cut	335.00 FL	*335.00 FL
33	2		*FRONT DOOR HINGE RH	Bent	336.00 FL	*336.00 FL
34	1		*FRONT DOOR CHECKER RH	Damaged	112.00 FL	*112.00 FL
35	1		*FRONT DOOR OUTER HANDLE RH	Cut	269.00 FL	*269.00 FL
36	1		*FRONT DOOR GLASS RH	Not Necessary	385.00 FL	*- FL
37	1		*FRONT DOOR INNER LOCK RH	Not Necessary	448.00 FL	*- FL
38	1		*FRONT DOOR INNER TRIM RH	Cracked	785.00 FL	*785.00 FL
39	1		*FRONT DOOR LOCK CATCHER RH	Not Necessary	98.00 FL	*- FL
40	1		*FRONT DOOR WEATHERSTRIP RH	Necessary	435.00 FL	*435.00 FL
41	1		*FRONT DOOR OUTER STRIP RH	Cut	188.00 FL	*188.00 FL
42	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	675.00 FL	*- FL
43	1		*FRONT DOOR REGULATOR RH	Damaged	798.00 FL	*405.00 FL
44	1		*FRONT DOOR QUARTER GARNISH RH	Cut	165.00 FL	*165.00 FL
45	1		*FRONT DOOR GLASS CHANNEL RH	Not Necessary	188.00 FL	*- FL
46	1		*SET FRONT BUMPER CLIP	Necessary	120.00 FS	*30.00 FS
47	1		*FRONT BUMPER WRAPPING PAPER (SPECIAL TYPE)	Necessary	800.00 FS	*380.00 FS
48	1		*SET FRONT BUMPER BOTTOM GARNISH CLIP	Not Necessary	80.00 FS	*- FS
49	1		*BONNET WRAPPING PAPER (SPECIAL TYPE)	Necessary	1,200.00 FS	*380.00 FS
50	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	80.00 FS	*30.00 FS
51	1		*SET FRONT FENDER INNER GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
52	1		*FRONT WINDSCREEN REPAIR KIT	Not Necessary	250.00 FS	*- FS
53	1		*FRONT FENDER WRAPPING PAPER RH (SPECIAL TYPE)	Necessary	600.00 FS	*380.00 FS
54	1		*FRONT DOOR RH SEALANT	Necessary	120.00 FS	*60.00 FS
55	1		*FRONT DOOR WRAPPING PAPER RH (SPECIAL TYPE)	Necessary	1,000.00 FS	*380.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET FRONT DOOR FRAME STEP GARNISH CLIP RH	Not Necessary	50.00 FS	*- FS
57	1		*SET FRONT DOOR INNER TRIM CLIP RH	Necessary	60.00 FS	*30.00 FS
58	1		*SET SIDE SKIRT CLIP RH	Not Necessary	60.00 FS	*- FS
59	1		*SIDE SKIRT WRAPPING PAPER (SPECIAL TYPE)	Not Necessary	600.00 FS	*- FS
60	1		*FRONT WHEEL TYRE RH	Cut	850.00 FS	*300.00 FS
61	1		*SET WHEEL CAP	Not Necessary	200.00 FS	*- FS
62	1		*BRAKE OIL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	52,627.00	28,882.00
- List Item Discount on L Items 10.00/10.00% (S\$)	4,641.70	2,688.20
Total Parts (S\$)	47,985.30	26,193.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,400.00	1,100.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	1,100.00
3	TUFF COAT	New	650.00	100.00
4	CONDUCT WATER LEAKAGE TEST	New	200.00	0.00
5	REMOVE & REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	380.00	0.00
6	WIRING CHECK	New	280.00	30.00
7	REFOCUS HEADLAMP BEAM	New	80.00	0.00
8	REMOVE AND REFIX DASHBOARD AND INTERNAL WIRING	New	850.00	0.00
9	REMOVE AND REFIX FRONT UNDERCARRIAGE INCLUDING CROSSMEMBER	New	1,800.00	280.00
10	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	800.00	150.00
11	TO PREDD FRONT WHEEL BEARING	New	120.00	0.00
12	FOUR WHEEL ALIGNMENT	New	180.00	80.00
13	RESET ABS LIGHT	New	600.00	0.00
14	REMOVE & REFIX FRONT WINDSCREEN	New	200.00	0.00
15	REMOVE & REFIX AUDIO SPEAKER	New	120.00	0.00
16	TRANSFER FRONT DOOR MECHANISM	New	80.00	80.00
17	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	580.00	0.00
Gross Labour Cost (S\$)			11,120.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >