

CB6173Z

Tojolu Hiale

TP AYA

Xin Yu

LH1726117652

Reer Bumper	Dented	465.10 ✓
Reer Bumper Clips	m	30(SN) ✓
Reer Bumper Side Holder x 02	m	45.1 x 2 = 90.20 ✓
Reer Bumper Reinforcement	Dented	285.10 ✓
Reverse Sensor	Dented	280(SN) 200(SN)
Reer End Panel	Dented	598.10 ✓
Reer End Panel Top Plate	Bent	158.20 ✓
Reer End Panel Sealant	Nec	60(SN) ✓
Taillup x 02	RH cracked	281.8 x 2 = 563.60 ✓ 281.80
Tailgate	Dented	1245.10 ✓
Tailgate Lock	Dented	234.50 ✓
Tailgate Lock Cover	cracked	58.20 ✓
Tailgate Weatherstripe	cut	219.20 ✓
Tailgate Glass Moulding	3 Nec	285.10 ✓
Tailgate Sealant		60(SN) ✓

CB6173Z.

60km/h stick.

Nec

15(SN) ✓

Spere Tyre Carrier

2 XHP
Nec

279.10.X

Spere Tyre lock Bolt.

52.40.X.

3921
294075

8-N: 365

Panel Beating
Spray Painting.

Wiring.

To remove upholstery.

To spray tuft coat

To remove reverse sensor

To transfer tailgate settings.

To remove tailgate glass

~~1200~~ 800

~~1200~~ 800

~~1000~~ 300

~~1500~~ 400

~~1500~~ 600

1960 ~~1000~~ 300

~~1500~~ 600

~~1500~~ 1000

total: 5265.75

4/8: 4.2K

06 Days.