



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOW GARNET			Ref: CS/ASM22010213/Awy3m4 Date: 20/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 4900K	Veh. Inspected	CB 6173Z
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S2M04CQU	Excess (\$)	0.00
	Assign From	LOW GARNET	Assign Date	14/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2985
	Engine No.	HIDDEN	Year of Reg.	2003
	Chassis No.	LH1726117652	Colour	SILVER
	Odometer	920197 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Front Tyre	195 R15C	YOKOHAMA	6 mm
	R/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
	L/H Rear Tyre	195 R15C	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/10/2022	Inspection Date	23/11/2022
	Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	