

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22010220/DNY3Q2
Date: 15/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00036642200
Claimant Vehicle No :	SMA6182J	Insured Vehicle No :	SJW2336D
Date of Loss:	11/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207308/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA6182J	Engine No:	27491031365746
Make & Model:	MERCEDES-BENZ C180, 1.6 (A)	Chassis No:	WDD2050402R389767
Reg. Date:	14/06/2018 (Man. Year: 2018)	Odometer:	89601 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,987.10	0.00	3,987.10	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	400.00	1,240.00	75.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,627.10	400.00	5,227.10	92.89
+ GST 7.00/7.00% (S\$)	393.90	28.00	365.90	92.89
Nett Amount (S\$)	6,021.00	428.00	5,593.00	92.89

INSPECTION

Date of Assignment:	13/10/2022	
Date Inspected:	25/10/2022	Inspected At: Accord Auto Services Pte Ltd (HQ) 10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point Singapore 568047
Estimated Period of Repair:	2.0 days	

Adjuster: BRYAN TANI

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2022)
Parts: M1-COUPE	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMA6182J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,020.00 FL	*- FL
2	1		*REAR BUMPER SIDE RETAINER LH -SHORT	Serviceable	74.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH -LONG	Serviceable	75.00 FL	*- FL
4	1		*REAR BUMPER LOWER	Not Necessary	275.00 FL	*- FL
5	1		*REAR BUMPER RH EXHAUST CHROME MOULDING	Not Necessary	315.00 FL	*- FL
6	1		*REAR BUMPER CENTRE CHROME MOULDING	Not Necessary	315.00 FL	*- FL
7	1		*REAR REINFORCEMENT BAR	Not Necessary	825.00 FL	*- FL
8	2		*REVERSE SENSOR	Serviceable	420.00 FL	*- FL
9	1		*SET REAR BUMPER CLIPS	Serviceable	50.00 FS	*- FS
10	1		*SET REAR FENDER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,419.00	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	431.90	0.00
Total Parts (\$\$)	3,987.10	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	600.00	200.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGE PARTS TO KNOCK ,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	200.00
3	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
4	TO REMOVE/REPLACE /REFIX REAR REVERSE SENSOR	New	120.00	0.00
			Gross Labour Cost (\$\$)	400.00
			1,640.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >