

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22010222/SVY3Q2
Date: 22/11/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00004192201
Claimant Vehicle No :	SMH8509B	Insured Vehicle No :	YQ101G
Date of Loss:	10/10/2022	Nature of Claim:	TP
		Claim No:	SNM22D207280/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH8509B	Engine No:	2ZR2B09115
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	ZVW508086009
Reg. Date:	12/02/2019 (Man. Year: 2018)	Odometer:	326528 km
Colour:	Brown		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	HARMONIC 6 mm	Rear Left Side:	HARMONIC 6 mm
Front Right Side:	HARMONIC 6 mm	Rear Right Side:	HARMONIC 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,772.53	2,200.00	1,572.53	41.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	630.00	650.00	50.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,052.53	2,830.00	2,222.53	43.99
Approved Total (Overridden) (S\$)		2,250.00		
Nett Amount (S\$)	5,052.53	2,250.00	2,802.53	55.47

INSPECTION

Date of Assignment:	13/10/2022	
Date Inspected:	18/10/2022	Inspected At: Trident Auto Service Centre Pte Ltd (HQ) 8 Kaki bukit Ave 4, #02-42 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	2.0 days	

Adjuster: S Mohamed Irfan Bin Mohamed Iqbal

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Nov 2022)
Parts:	144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH8509B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented	886.90 FL	*880.00 FL
2	1		*FRONT BONNET LOCK	Dented	158.90 FL	*150.00 FL
3	1		*FRONT BONNET INSULATOR	Not Necessary	296.80 FL	*- FL
4	2		*BONNET HINGES	Not Necessary	173.60 FL	*- FL
5	1		*FRONT HEADLAMP RH	Broken	1,895.60 FL	*1,800.00 FL
6	1		*FRONT BUMPER	Repair	1,339.78 FL	*- FL
7	1		*FRONT BUMPER LOGO	Cut	91.80 FL	*50.00 FL
8	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*40.00 FS
9	1		*SET BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,983.38	2,920.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,210.85	720.00
Total Parts (\$)	3,772.53	2,200.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	600.00	200.00
2	TO PUTTY AND RESPRAY ON ACCIDENT PORTION	New	600.00	400.00
3	TO CHECK WIRING & FOCUS HEADLAMP	New	80.00	30.00
Gross Labour Cost (S\$)			1,280.00	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >