

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22010224/EQY3M4**Date:** 19/12/2022REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00068292204		
<b>Claimant Vehicle No :</b>	SFP1777E	<b>Insured Vehicle No :</b>	GBD1200M		
Date of Loss:	12/10/2022	Nature of Claim:	TP	Claim No:	SNM22D207317/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFP1777E</b>		Engine No:	170623W1198204DTD
Make & Model:	JAGUAR XE, 2.0 D L I4D (A)		Chassis No:	SAJAB4AN8JCP25671
Reg. Date:	29/11/2017 (Man. Year: 2017)		Odometer:	106170 km
Colour:	Grey			
Engine Capacity:	1999 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R16	Rear Tyre Size:	215/50 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,608.80	3,853.53	6,755.27	63.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,741.00	4,571.00	7,170.00	61.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>22,349.80</b>	<b>8,424.53</b>	<b>13,925.27</b>	<b>62.31</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,564.49</b>	<b>589.72</b>	<b>974.77</b>	<b>62.31</b>
<b>Nett Amount (S\$)</b>	<b>23,914.29</b>	<b>9,014.25</b>	<b>14,900.04</b>	<b>62.31</b>

INSPECTION

Date of Assignment:	13/10/2022		
Date Inspected:	19/10/2022	Inspected At:	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103
Estimated Period of Repair:	4.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2022)
<b>Parts:</b> 143	JAGUAR XE 2.0 D L I4D (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SFP1777E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-BUMPER REAR	Broken	1,325.30 FS	*1,192.77 FS
2	1		*PANEL-VALANC	Cut	609.80 FS	*548.82 FS
3	1		*MOUNTING-BRACKET LH	Not Necessary	143.00 FS	*- FS
4	1		*MOUNTING-BRACKET RH	Not Necessary	143.00 FS	*- FS
5	1		*TOW COVER REAR XE	Crushed	37.20 FS	*33.48 FS
6	1		*CAP-END RH	Not Necessary	24.00 FS	*- FS
7	1		*CAP-END LH	Not Necessary	24.00 FS	*- FS
8	1		*MOUNTING-BRACKET CTR	Not Necessary	120.00 FS	*- FS
9	1		*PIPE&SILENCR	Not Necessary	1,787.10 FS	*- FS
10	1		*CLAMP	Not Necessary	99.20 FS	*- FS
11	1		*HEATSHIELD LH	Not Necessary	271.60 FS	*- FS
12	1		*HEATSHIELD LH	Not Necessary	65.90 FS	*- FS
13	1		*TRUNK LIP XE	Repair	1,858.10 FS	*- FS
14	1		*BUMPER BEAM REAR XE	Bent	753.50 FS	*678.15 FS
15	1		*BADGE REAR XE	Necessary	136.90 FS	*123.21 FS
16	1		*BADGE	Necessary	250.60 FS	*225.54 FS
17	1		*BADGE	Necessary	131.60 FS	*118.44 FS
18	1		*LAMP-TAIL LH	Broken	593.40 FS	*534.06 FS
19	1		*FOG LAMP REAR LH XE	Broken	443.40 FS	*399.06 FS
20	4		*PARKING AID SENSOR R	Not Necessary	1,259.20 FS	*- FS
21	1		*HARNESS REAR BUMPER	Not Necessary	532.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>10,608.80</b>	<b>3,853.53</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, REAR BOOTLID, VALANCE REAR, REAR BUMPER BEAM, SENSORS, TAILLAMP, BOOTLAMP, REAR EXHAUST, ETC	New	6,500.00	1,950.00
2	TO SPRAYPAINT ON REAR BUMPER, BOOTLID, REAR FENDER LH, BUMPER BEAM, ETC	New	4,000.00	2,000.00
3	TO REMOVE, REFIT & TRANSFER BOOTLID COMPONENTS	New	500.00	0.00
4	NUMBER PLATE & HOLDER	New	120.00	0.00
5	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	621.00	621.00
			<b>Gross Labour Cost (S\$)</b>	<b>11,741.00</b>
				<b>4,571.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >