

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI22010227/UVY3E2**Date:** 06/01/2023**REFERENCE**

Insured/Claimant: **ANGLO-AMERICAN
TRANSPORTATION PTE LTD**

Policy No: DMB1SNW00014882203**Date of Loss:** 11/10/2022

**Nature of
Claim:** OD

**Claim
No:** SNM22D207348/C01/KOHNGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No:** **PC3069C****Make & Model:** NISSAN NV350, 2.5 D HR MICROBUS (A)**Engine No:** YD25351421A**Reg. Date:** 13/09/2014 (Man. Year: 2014)**Chassis No:** JN1UC4E26Z0001867**Colour:** Silver**Odometer:** 605105 km**Engine Capacity:** 2488 cc**Market Value/New Car Price:** S\$19,000.00**Sum Insured (S\$):** **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes

Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES**Front Tyre Size:** 195 R15**Rear Tyre Size:** 195 R15**Front Left Side:** Bridgestone 5 mm**Rear Left Side:** Michelin 5 mm**Front Right Side:** Michelin 5 mm**Rear Right Side:** Condor 5 mm*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	9,680.00	-9,680.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	1,651.08	-1,651.08	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	11,331.08	-11,331.08	
- Excess (S\$)	0.00	2,000.00	-2,000.00	
(S\$)	0.00	9,331.08	-9,331.08	
+ GST 7.00/7.00% (S\$)	0.00	653.18	-653.18	
Nett Amount (S\$)	0.00	9,984.26	-9,984.26	

INSPECTION

Date of Assignment: 14/10/2022 **Present Location:** Jin Auto Services Pte Ltd (Defu)

Date Inspected: 17/10/2022 **Inspected At:** Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 10.0 days**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$5,130.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 06 Jan 2023)	
Parts:	N/A	NISSAN NV350 2.5 D HR MICROBUS (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3069C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*L/BUMPER GRILLE	Torn	-	*80.00 F
2	1		*R/BUMPER GRILLE	Torn	-	*80.00 F
3	1		*FRONT NUMBER PLATE	Bent	-	*20.00 F
4	1		*FRONT BUMPER	Distorted	-	*380.00 F
5	1		*TOW BAR COVER	Deformed	-	*25.00 F
6	1		*L/F OUT BUMPER BRKT	Bent	-	*80.00 F
7	1		*R/F OUT BUMPER BRKT	Bent	-	*80.00 F
8	1		*FRONT GRILLE	Broken / Missing	-	*400.00 F
9	1		*GRILLE BADGE	Missing	-	*65.00 F
10	1		*BONNET	Badly Dented	-	*680.00 F
11	1		*LEFT HEADLAMP ASSY	Cracked	-	*300.00 F
12	1		*RIGHT HEADLAMP ASSY	Cracked	-	*300.00 F
13	1		*L/F FOG LAMP CPL	* Check	-	*- F
14	1		*R/F FOG LAMP CPL	Cracked	-	*250.00 F
15	1		*R/F WING	Dented	-	*260.00 F
16	1		*FRT BUMPER SUPPORT	Bent	-	*380.00 F
17	1		*LWR WINDSCREEN COVER	* Check	-	*- F
18	1		*WINDSCREEN	Cracked	-	*750.00 F
19	1		*WINDSCREEN SEAL (NPA)	Necessary	-	*- F
20	1		*WINDSCREEN BOND KIT (NPA)	Necessary	-	*- F
21	1		*FRT SCREEN MNTG KIT (NPA)	Necessary	-	*- F
22	1		*PASSENGER AIRBAG	Activated	-	*1,500.00 F
23	1		*HEATER CPL	* Check	-	*- F
24	1		*HEATER BLOWER	* Check	-	*- F
25	1		*L/F SEAT BELT	Activated	-	*600.00 F
26	1		*R/F SEAT BELT	Activated	-	*600.00 F
27	1		*AIRBAG CONTROL UNIT	* Check	-	*- F
28	1		*DRIVER AIRBAG	Activated	-	*1,400.00 F
29	1		*RADIATOR	* Check	-	*- F
30	1		*FAN SHROUD	* Check	-	*- F
31	1		*TURBOCHARGER COOLER O/S	Punctured	-	*1,450.00 F
					Total Parts (\$)	0.00 9,680.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	194.0 WU X 42.00 SGD/H	New	-	814.80
2	LABOUR COST 125.0 WU X 42.00 SGD/H	New	-	525.00
3	MATERIAL COST	New	-	191.28
4	FIXED RATE	New	-	120.00
Gross Labour Cost (\$\$)			0.00	1,651.08

Report was unsubmitted during this print-out.

< END OF ESTIMATES >