

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010228/AYA3Q2**Date:** 10/07/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800065771
Claimant Vehicle No :	YQ4552L	Insured Vehicle No :	SMC490Z
Date of Loss:	08/10/2022	Nature of Claim:	TP
		Claim No:	3741634019SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ4552L		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1GD8804814
Reg. Date:	24/09/2021 (Man. Year: 2021)	Chassis No:	JHHAGV46X0K001072
Colour:	Silver	Odometer:	25708 km
Engine Capacity:	2755 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/75 R15	Rear Tyre Size:	175/75 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,293.20	5,640.90	3,652.30	39.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,850.00	1,570.00	1,280.00	44.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,143.20	7,210.90	4,932.30	40.62
Approved Total (Overridden) (S\$)		5,700.00		
(S\$)	12,143.20	5,700.00	6,443.20	53.06
+ GST 7.00/7.00% (S\$)	850.02	399.00	451.02	53.06
Nett Amount (S\$)	12,993.22	6,099.00	6,894.22	53.06
+ Loss of Use (7.0 x S\$120.00/day) (S\$)		840.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,941.00		
Global Sum Settlement (S\$)		5,500.00		

INSPECTION

Date of Assignment:	10/10/2022	SM Automotive (HQ)
Date Inspected:	10/10/2022 Inspected At:	BLK C, 1 KAKI BUKIT AVENUE 6 #01-43
Estimated Period of Repair:	6.0 days	SINGAPORE 417883

Adjuster: ADRIAN LING**Manager:** Ezlyna

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	570.80 FL	*570.80 FL
2	1		*RH FRONT BUMPER BRACKET	Bent	368.10 FL	*265.00 FL
3	1		*RH FRONT BUMPER FOG LAMP COVER	Not Necessary	121.90 FL	*- FL
4	1		*RH FRONT HEADLAMP	Cracked	971.20 FL	*971.20 FL
5	1		*RH FRONT HEADLAMP LOWER RUBBER	Not Necessary	61.10 FL	*- FL
6	1		*RH FRONT CORNER PANEL	Cracked	370.10 FL	*370.10 FL
7	1		*FRONT GRILLE	Not Necessary	789.20 FL	*- FL
8	1		*FRONT GRILLE LOGO	Not Necessary	121.20 FL	*- FL
9	1		*RH FRONT DOOR	Dented	1,718.90 FL	*1,580.00 FL
10	1		*RH FRONT DOOR HINGE	Not Necessary	230.30 FL	*- FL
11	1		*RH FRONT DOOR CHECKER	Not Necessary	268.90 FL	*- FL
12	1		*RH FRONT DOOR INNER TRIM BOARD	Not Necessary	978.10 FL	*- FL
13	1		*RH FRONT DOOR WIND MIRROR	Cut	678.90 FL	*678.90 FL
14	1		*RH FRONT STEP PANEL	Repair	570.10 FL	*- FL
15	1		*RH FRONT STEP PANEL GARNISH	Cracked	378.40 FL	*295.00 FL
16	1		*RH FRONT UPPER ARM	Bent	990.20 FL	*680.00 FL
17	1		*RH FRONT LOWER ARM	Bent	470.10 FL	*470.10 FL
18	1		*RH FRONT KNUCKLER ARM	Damaged	781.20 FL	*781.20 FL
19	1		*RH FRONT KNUCKLER ARM BEARING	Damaged	220.80 FL	*220.80 FL
20	1		*RH FRONT SHOCK ABSORBER	Damaged	278.10 FL	*278.10 FL
21	1		*RH FRONT RIM	Cut	650.00 FS	*250.00 FS
22	1		*RH FRONT TYRE	Not Necessary	320.00 FS	*- FS
23	1		*RH FRONT CORNER PANEL CLIPS	Necessary	40.00 FS	*20.00 FS
24	1		*RH FRONT DOOR INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	12,027.60	7,431.20
- List Item Discount on L Items 25.00/25.00% (S\$)	2,734.40	1,790.30
Total Parts (S\$)	9,293.20	5,640.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,000.00	600.00
2	LABOUR FOR SPRAY PAINTING	New	900.00	500.00
3	LABOUR FOR REMOVE & TRANSFER RH FRONT DOOR FITTING	New	200.00	80.00
4	TO APPLY TUFF COATING / RUST PROOF ACCIDENT AREAS	New	200.00	60.00
5	LABOUR FOR REMOVE & RENEW RH FRONT UNDER CARRIAGE	New	300.00	220.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
7	WIRING	New	100.00	30.00
Gross Labour Cost (S\$)			2,850.00	1,570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >