

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010229/APA3Q2**Date:** 03/05/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100458590
Claimant Vehicle No :	GBA36T	Insured Vehicle No :	SLB1632S
Date of Loss:	08/10/2022	Nature of Claim:	TP
		Claim No:	9164311270SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA36T		
Make & Model:	TOYOTA HIACE, 3.0 D TURBO 5DR (M)	Engine No:	1KD2747885
Reg. Date:	12/10/2017 (Man. Year: 2017)	Chassis No:	JTFHT02P700233532
Colour:	Blue	Odometer:	100358 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Windforce 6 mm	Rear Left Side:	Windforce 6 mm
Front Right Side:	Windforce 6 mm	Rear Right Side:	Windforce 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,609.81	3,686.20	2,923.61	44.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,230.00	1,830.00	400.00	17.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,839.81	5,516.20	3,323.61	37.60
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	8,839.81	4,400.00	4,439.81	50.23
+ GST 8.00/8.00% (S\$)	707.18	352.00	355.18	50.22
Nett Amount (S\$)	9,546.99	4,752.00	4,794.99	50.23
+ Loss of Use (8.0 x S\$80.00/day) (S\$)		640.00		
Nett Liability (S\$)		5,392.00		
Global Sum Settlement (S\$)		5,390.00		

INSPECTION

Date of Assignment:	11/10/2022		
Date Inspected:	11/10/2022	Inspected At:	J-mart Motor Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-578 Singapore 539186
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,150.00 FL	*1,714.00 FL
2	1		*TAILGATE LOCK	Jammed	275.00 FL	*275.00 FL
3	1		*LOGO EMBLEM	Necessary	72.20 FL	*72.20 FL
4	1		*TAILGATE OUTER HANDLE	Not Necessary	165.00 FL	*- FL
5	1		*TAILGATE W/STRIP	Cut	395.00 FL	*395.00 FL
6	1		*TAILGATE TRIMBOARD	Cut	182.80 FL	*182.80 FL
7	1		*TAILLAMP	N/S Cut	601.60 FL	*300.80 FL
8	1		*REAR BUMPER	Deformed	595.00 FL	*595.00 FL
9	2		*REAR BUMPER RETAINERS	Necessary	130.00 FL	*130.00 FL
10	4		*REAR BUMPER LOWER BRACKET	Bent	120.00 FL	*120.00 FL
11	6		*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
12	1		*END PANEL INNER	Repair	1,155.00 FL	*- FL
13	1		*END PANEL OUTER	Dented	531.70 FL	*531.70 FL
14	1		*SPARE TYRE TRAY	Not Necessary	319.35 FL	*- FL
15	1		*SPARE TYRE SCREW	Not Necessary	40.00 FL	*- FL
16	1		*END PANEL INNER GARNISH	Dented	175.10 FL	*175.10 FL
17	2		*APRON PANEL	Not Necessary	290.00 FL	*- FL
18	2		*APRON PANEL RIVET	Not Necessary	32.00 FL	*- FL
19	1		*REAR W/SCREEN GUM	Necessary	50.00 FS	*50.00 FS
20	1		*REAR NO PLATE	Dented	40.00 FS	*30.00 FS
21	1		*CAMERA	Not Necessary	400.00 FS	*- FS
22	1		*REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS
23	1		*70KM/H STICKER	Necessary	25.00 FS	*15.00 FS
24	1		*WOODEN WOOD	Not Necessary	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,424.75	4,816.60
- List Item Discount on L Items 25.00/25.00% (S\$)	1,814.94	1,130.40
Total Parts (S\$)	6,609.81	3,686.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,000.00	800.00
2	SPRAY PAINTING	New	1,000.00	800.00
3	TRANSFER TAILGATE FITTING	New	80.00	80.00
4	REMOVE & REFIT REAR W/SCREEN	New	120.00	120.00
5	WIRING	New	30.00	30.00
Gross Labour Cost (S\$)			2,230.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >