

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG22010232/RPA3Q2**Date:** 10/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900150384
Claimant Vehicle No :	SHC4958A	Insured Vehicle No :	SMP1898G
Date of Loss:	11/10/2022	Nature of Claim:	TP
		Claim No:	7568303654SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4958A	Engine No:	2ZR6540632
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U405766421
Reg. Date:	16/10/2015 (Man. Year: 2015)	Odometer:	775364 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,994.60	2,516.93	8,477.67	77.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,992.00	900.00	1,092.00	54.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,986.60	3,416.93	9,569.67	73.69
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	12,986.60	2,900.00	10,086.60	77.67
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$102.72/day) (S\$)		616.32		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,818.32		
Global Sum Settlement (S\$)		3,810.00		

INSPECTION

Date of Assignment:	12/10/2022	
Date Inspected:	12/10/2022	Inspected At: Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FRT (DISC 25%)	Cut	602.60 F	*451.95 F
2	10		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%)	Necessary	48.00 F	*36.00 F
3	1		*COVER ,FR BUMPER HOLE RH (DISC 25%)	Scratched	21.40 F	*16.05 F
4	1		*BUMPER GRILLE SUB-ASSY LOWER (DISC 25%)	Cracked	389.90 F	*292.43 F
5	1		*EMBLEM FRONT (DISC 25%)	Missing	98.70 F	*74.03 F
6	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Cracked	97.60 F	*73.20 F
7	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Bent	567.90 F	*425.93 F
8	1		*BUMPER FRT ABSORBER LOWER (DISC 25%)	Cracked	159.30 F	*119.48 F
9	1		*HEADLAMP RH (DISC 10%)	Cut	1,075.40 F	*967.86 F
10	1		*NUMBER PLATE FRAME (SN)	Cracked	25.00 F	*25.00 F
11	1		*NUMBER PLATE (SN)	Bent	35.00 F	*35.00 F
12	1		*BUMPER SUPPORT F/RH	Not Necessary	86.20 F	*- F
13	1		*BUMPER SUPPORT F/LH	Not Necessary	86.20 F	*- F
14	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	97.60 F	*- F
15	1		*BUMPER REINFORCEMENT FRT	Not Necessary	567.90 F	*- F
16	1		*ARM SUB-ASSY FR BUMPER LH	Not Necessary	284.00 F	*- F
17	1		*ARM SUB-ASSY FR BUMPER RH	Not Necessary	284.00 F	*- F
18	1		*DEFLECTOR RADIATOR RH	Not Necessary	94.30 F	*- F
19	1		*DEFLECTOR RADIATOR LH	Not Necessary	86.90 F	*- F
20	1		*BRACKET ,FR BUMPER	Not Necessary	126.10 F	*- F
21	1		*COVER ,FR BUMPER HOLE LH	Not Necessary	21.40 F	*- F
22	1		*FOG LAMP RH	Not Necessary	335.60 F	*- F
23	1		*FOG LAMP LH	Not Necessary	319.30 F	*- F
24	1		*HOOD END PANEL SEAL	Not Necessary	80.60 F	*- F
25	1		*COVER ,RADIATOR	Not Necessary	139.30 F	*- F
26	1		*GRILLE ,RADIATOR	Not Necessary	389.30 F	*- F
27	1		*GRILLE ,RADIATOR LOWER NO.2	Not Necessary	118.30 F	*- F
28	1		*BUMPER LIP FRT	Not Necessary	182.70 F	*- F
29	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	159.30 F	*- F
30	1		*UNDER COVER CENTER	Not Necessary	511.20 F	*- F
31	1		*HEAD LAMP LH	Not Necessary	1,075.40 F	*- F
32	1		*SUPPORT SUB-ASSY	Repair	1,839.70 F	*- F
33	1		*HOOD PANEL	Repair	988.50 F	*- F

F=Franchise part.

Total Parts (S\$) **10,994.60** **2,516.93**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	936.00	500.00
3	TO WASH AND VACUUM	New	60.00	0.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	100.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			1,992.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >