

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22010234/AYA3Q2**Date:** 20/04/2023REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210130480
Claimant Vehicle No :	SJQ1035K	Insured Vehicle No :	SMG2449K
Date of Loss:	14/10/2022	Nature of Claim:	TP
		Claim No:	2624878434SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ1035K	Engine No:	R18A1762068
Make & Model:	HONDA STREAM, 1.8 RSZ (A)	Chassis No:	RN61055504
Reg. Date:	24/04/2009 (Man. Year: 2008)	Odometer:	180227 km
Colour:	Silver		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,018.40	14,037.04	10,981.36	43.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,230.00	5,090.00	4,140.00	44.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,248.40	19,127.04	15,121.36	44.15
Approved Total (Overridden) (S\$)		15,300.00		
Nett Amount (S\$)	34,248.40	15,300.00	18,948.40	55.33
+ Car Rental (15.0 x S\$120.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		17,187.45		
Global Sum Settlement (S\$)		17,000.00		

INSPECTION

Date of Assignment:	14/10/2022	HD Perfect Autowork Pte Ltd (HQ)
Date Inspected:	14/10/2022 Inspected At:	8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Estimated Period of Repair:	15.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	638.90 FL	*638.90 FL
2	2		*BONNET HINGE	Bent	138.00 FL	*138.00 FL
3	1		*BONNET LOCK	Damaged	85.10 FL	*85.10 FL
4	1		*BONNET LOCK COVER GARNISH	Deformed	48.60 FL	*48.60 FL
5	1		*BONNET LOCK CABLE	Not Necessary	125.30 FL	*- FL
6	1		*BONNET INSULATOR	Not Necessary	97.80 FL	*- FL
7	2		*BONNET STOPPER	Not Necessary	48.00 FL	*- FL
8	1		*BONNET RUBBER	Cut	98.40 FL	*98.40 FL
9	1		*FRONT FENDER	N/S Buckled	1,870.80 FL	*582.00 FL
10	1		*FRONT FENDER TOP INNER GARNISH	N/S Deformed	315.40 FL	*157.70 FL
11	2		*FRONT FENDER INNER COWLING	Not Necessary	159.00 FL	*- FL
12	1		*FRONT BUMPER	Distorted	639.60 FL	*639.60 FL
13	2		*FRONT BUMPER FOGLAMP	Cracked	486.20 FL	*486.20 FL
14	2		*FRONT BUMPER FOGLAMP COVER	Not Necessary	95.80 FL	*- FL
15	1		*FRONT BUMPER REINFORCEMENT	Dented	318.90 FL	*318.90 FL
16	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	87.10 FL	*- FL
17	2		*FRONT BUMPER SIDE RETAINER	Necessary	68.40 FL	*68.40 FL
18	1		*CENTRE GRILLE	Cracked	196.80 FL	*196.80 FL
19	1		*CENTRE GRILLE CHROME	Cut	210.30 FL	*210.30 FL
20	1		*CENTRE GRILLE LOGO	Necessary	42.60 FL	*42.60 FL
21	2		*HEADLAMP	Cracked	1,360.00 FL	*1,360.00 FL
22	1		*HEADLAMP LOWER BRACKET	N/S Cracked	79.00 FL	*39.50 FL
23	1		*FRONT SUPPORT PANEL TOP GARNISH	Deformed	94.60 FL	*94.60 FL
24	1		*FRONT SUPPORT PANEL	Buckled	546.20 FL	*546.20 FL
25	1		*ENGINE UNDER COVER GARNISH	Not Necessary	254.30 FL	*- FL
26	1		*RADIATOR	Cracked	1,367.50 FL	*1,367.50 FL
27	2		*RADIATOR BRACKET	Bent	90.00 FL	*90.00 FL
28	2		*RADIATOR TOP BRACKET MOUNTING	Necessary	38.00 FL	*38.00 FL
29	1		*RADIATOR FAN BLADE	Not Necessary	198.80 FL	*- FL
30	1		*RADIATOR FAN MOTOR	Damaged	476.90 FL	*298.00 FL
31	1		*RADIATOR FAN COWLING	Cracked	217.60 FL	*217.60 FL
32	1		*RADIATOR SPARE TANK	Not Necessary	246.90 FL	*- FL
33	2		*RADIATOR HOSE	Not Necessary	170.00 FL	*- FL
34	1		*AIRCON CONDENSER	Dented	826.60 FL	*826.60 FL
35	2		*AIRCON CONDENSER TOP BRACKET	Bent	45.60 FL	*45.60 FL
36	1		*AIRCON GARNISH WITH COWLING	Not Necessary	194.30 FL	*- FL
37	4		*AIRCON CONDENSOR TOP BRACKET MOUNTING	Necessary	76.00 FL	*76.00 FL
38	1		*AIRCON COMPRESSOR PRESSURE HOSE	Not Necessary	356.00 FL	*- FL
39	1		*AIRCON COMPRESSOR SUCTION	Not Necessary	328.00 FL	*- FL
40	1		*RESONATOR BOX	Not Necessary	278.90 FL	*- FL
41	1		*RESONATOR DUCT	Not Necessary	88.40 FL	*- FL
42	1		*MANIFOLD 02 SENSOR	Not Necessary	468.00 FL	*- FL
43	1		*MANIFOLD COVER	Not Necessary	137.00 FL	*- FL
44	2		*HORN	Not Necessary	152.40 FL	*- FL
45	1		*TAILGATE	Distorted	903.20 FL	*903.20 FL
46	1		*TAILGATE LOGO	Necessary	41.90 FL	*41.90 FL
47	1		*TAILGATE EMBLEM STREAM	Necessary	31.60 FL	*31.60 FL
48	2		*TAILGATE NUMBER PLATE LAMP	Not Necessary	172.00 FL	*- FL
49	1		*TAILGATE OUTER GARNISH	Cracked	184.30 FL	*184.30 FL
50	1		*TAILGATE OUTER HANDLE	Not Necessary	84.20 FL	*- FL
51	1		*TAILGATE EMBLEM RSZ	Necessary	98.50 FL	*98.50 FL
52	1		*TAILGATE INNER LOCK	Damaged	109.80 FL	*109.80 FL
53	1		*TAILGATE WEATHER STRIP	Cut	171.60 FL	*171.60 FL
54	2		*TAILGATE STOPPER	Not Necessary	48.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
55	1		*TAILGATE INNER HANDLE	Missing	29.00 FL	*29.00 FL
56	1		*TAILGATE INNER BOARD	Cracked	296.70 FL	*296.70 FL
57	2		*TAILGATE DAMPER	Not Necessary	300.20 FL	*- FL
58	1		*TAILGATE WINDSCREEN MOULDING	Necessary	164.30 FL	*164.30 FL
59	2		*TAILLAMP	N/S Cracked / O/S Cut	715.00 FL	*715.00 FL
60	4		*TAILLAMP BOLT COVER	Not Necessary	50.80 FL	*- FL
61	1		*REAR BUMPER	Distorted	688.90 FL	*688.90 FL
62	2		*REAR BUMPER CENTER BRACKET	Bent	130.00 FL	*130.00 FL
63	1		*REAR BUMPER TOW HOOK COVER	Deformed	19.20 FL	*19.20 FL
64	2		*REAR BUMPER SIDE RETAINER	Necessary	58.80 FL	*58.80 FL
65	2		*REAR FENDER INNER TRIM	Cracked	594.00 FL	*594.00 FL
66	1		*REAR END PANEL	Distorted	459.00 FL	*459.00 FL
67	1		*REAR END PANEL TOP GARNISH	Deformed	116.70 FL	*116.70 FL
68	1		*REAR END PANEL BOTTOM (CENTRE)	Deformed	325.00 FL	*325.00 FL
69	1		*REAR FLOOR PANEL	Buckled	597.00 FL	*597.00 FL
70	1		*REAR FLOOR MAT	Not Necessary	394.70 FL	*- FL
71	2		*REAR FLOOR PANEL COVER BOARD	Deformed	253.00 FL	*253.00 FL
72	1		*REAR FLOOR PANEL COVER BOARD (INNER SUPPORT)	Cracked	697.60 FL	*302.00 FL
73	1		*REAR TOOLS SPONGE	Cracked	196.40 FL	*196.40 FL
74	1		*REAR JACK COVER GARNISH	Deformed	185.00 FL	*185.00 FL
75	1		*REAR CHASSIS MEMBER RH	Repair	1,426.80 FL	*- FL
76	1		*REAR SPARE TYRE BRACKET	Bent	121.60 FL	*45.00 FL
77	1		*REAR SPARE TYRE HOLDER	Bent	171.80 FL	*171.80 FL
78	1		*CENTER EXHAUST INSULATOR	Not Necessary	69.20 FL	*- FL
79	1		*CENTRE EXHAUST GASKET	Not Necessary	60.00 FL	*- FL
80	1		*EXHAUST CENTER PIPE	Not Necessary	694.80 FL	*- FL
81	1		*REAR EXHAUST PIPE	Bent	709.50 FL	*690.00 FL
82	4		*REAR EXHAUST MOUNTING	Not Necessary	116.80 FL	*- FL
83	1		*REAR EXHAUST INSULATOR	Not Necessary	89.10 FL	*- FL
84	1		*REAR EXHAUST GASKET	Necessary	60.00 FL	*45.00 FL
85	1		*FRONT NUMBER PLATE (SPECIAL TYPE)	Cracked	180.00 FS	*60.00 FS
86	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
87	1		*SET BONNET INSULATOR CLIPS	Not Necessary	50.00 FS	*- FS
88	1		*SET CENTRE GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
89	1		*SET FRONT FENDER TOP INNER GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
90	1		*SET FRONT FENDER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
91	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
92	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
93	1		*RADIATOR COOLANT	Necessary	60.00 FS	*40.00 FS
94	1		*REAR NUMBER PLATE (SPECIAL TYPE)	Not Necessary	180.00 FS	*- FS
95	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
96	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
97	1		*SET TAILGATE OUTER GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
98	1		*SET TAILGATE INNER BOARD CLIP	Necessary	50.00 FS	*30.00 FS
99	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
100	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
101	1		*TAILGATE SOUND PROOF (SPECIAL TYPE)	Necessary	450.00 FS	*60.00 FS
102	1		*SET TAILGATE SPEAKER	Not Necessary	300.00 FS	*- FS
103	1		*SET TAILLAMP CLIP	Necessary	40.00 FS	*20.00 FS
104	1		*SET REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*50.00 FS
105	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
106	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
107	1		*REAR FLOOR PANEL INSULATION SEAL	Necessary	350.00 FS	*40.00 FS
108	1		*REAR FLOOR PANEL SOUND PROOF (OUTER) (SPECIAL TYPE)	Necessary	350.00 FS	*200.00 FS
109	1		*JACK	Not Necessary	150.00 FS	*- FS
110	1		*SET REAR JACK COVER GARNISH CLIP	Necessary	30.00 FS	*10.00 FS
111	1		*SPARE TYRE	Not Necessary	350.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
112	1		*SPARE TYRE RIM	Not Necessary	150.00 FS	*- FS
113	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
114	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS
115	1		*REAR FLOOR PANEL SOUND PROOF (INNER) (SPECIAL TYPE)	Not Necessary	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,118.00	17,303.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,099.60	3,266.76
Total Parts (\$\$)	25,018.40	14,037.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS (FRONT)	New	1,800.00	1,000.00
2	TO SPRAY PAINT AFFECTED AREA (FRONT)	New	1,400.00	900.00
3	REFOCUS HEADLAMP BEAM (FRONT)	New	60.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS (FRONT)	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST (FRONT)	New	80.00	60.00
6	TO PANEL BEAT, REMOVE AND REPLACE PARTS (REAR)	New	2,200.00	1,400.00
7	TO SPRAY PAINT AFFECTED AREA (REAR)	New	1,600.00	1,100.00
8	TUFF COAT (REAR)	New	250.00	100.00
9	WIRING AND BULB CHECK (REAR)	New	180.00	30.00
10	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY & ROOF LINING TO FACILIATE REPAIR (REAR)	New	350.00	80.00
11	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING (REAR)	New	80.00	50.00
12	REAR CHASSIS ALIGNMENT (REAR)	New	250.00	0.00
13	TRANSFER TAILGATE MECHANISM (REAR)	New	80.00	80.00
14	REMOVE AND REFIX TAILGATE WINDSCREEN (REAR)	New	120.00	120.00
15	REMOVE AND REFIX TAILGATE SPOILER (REAR)	New	100.00	0.00
16	CONDUCT WATER LEAKAGE TEST (REAR)	New	120.00	0.00
17	REMOVE AND REFIX REAR EXHAUST PIPE (REAR)	New	180.00	80.00
18	REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT (REAR)	New	80.00	0.00
19	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS. RESET MEMORIES TO SPECIFICATION ETC (REAR)	New	180.00	0.00
Gross Labour Cost (\$\$)			9,230.00	5,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >