

# MG SOLUTION PTE LTD

23 KAKI BUKIT AVENUE 4 (SOUTH WING) #02.03  
SINGAPORE 415933

TP 111  
Xiao Tony.

Vehicle No. SMK<sup>365517</sup>~~655D~~ TOYOTA WISH JTDGG20W10J005387

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	REAR NUMBER PLATE LAMP @64.20	cruld	128.40	✓
2	REAR BUMPER	Distorted	596.90	✓
3	REAR BUMPER SIDE HOLDER @35.40	Distorted	70.80	✓
4	REAR BUMPER REFLECTOR @56.20	LH cruld	112.40	56.20 ✓
5	REAR BUMPER IMPACT BRACKET @68.40	Distorted	136.80	✓
6	REAR END PANEL	Distorted	542.20	✓
7	REAR END PANEL TOP GARNISH	Distorted	286.60	✓
8	REAR END PANEL ANTENNA SENSOR		161.70	✓
9	TAILLAMP @379.20	cruld	758.40	✓
10	TAILLAMP LOWER BRACKET @45.40	cruld	90.80	✓
11	TAILLAMP PANEL @278.90	LH Distorted	557.80	278.90 ✓
12	TAILGATE	Distorted	1307.50	✓
13	TAILGATE LOCK	Tam d	374.40	✓
14	TAILGATE WEATHERSTRIPE	cr	329.10	✓
15	TAILGATE HINGE @98.70	But	197.40	✓
16	TAILGATE DAMPER @265.60	cruld	531.20	✓
17	TAILGATE REFLECTOR @277.60	Scratched	555.20	✓
18	TAILGATE INNER TRIM BOARD	Del d	485.50	✓
19	TAILGATE INNER SIDE TRIM BOARD @209.20	lt	418.40	✓
20	TAILGATE INNER TOP TRIM BOARD	Del d New	221.40	✓
21	TAILGATE OUTER CHROME MOULDING	cruld	321.70	✓
22	TAILGATE WIPER MOTOR	cruld	398.70	✓
23	TAILGATE WIPER ARM	cr	66.20	✓
24	TAILGATE WIPER ARM COVER	cr	15.40	✓
25	TAILGATE GLASS	Shattered	1029.40	✓
26	TAILGATE GLASS MOULDING	cr	162.10	✓
27	TAILGATE TOP SPOILER	Revis	950.80	+
28	TAILGATE TOP SPOILER BRAKE LAMP	New	241.40	+
29	TOYOTA LOGO	Free	60.40	✓
30	EMBLEM		41.70	✓
31	REAR LH FENDER	Distorted	955.80	✓
32	REAR FENDER INNER TRIM BOARD @434.20	cruld	868.40	✓
33	REAR FENDER INNER TRIM BOARD UPPER @265	cruld	530.00	✓
34	REAR FENDER INNER SHIELD @142.60	cruld	285.20	✓
35	REAR LH FENDER GLASS	Shattered	645.90	✓
36	REAR LH FENDER AIR VENT	Del d	62.90	✓
37	REAR LH FENDER WHEEL HOUSE PANEL	Revis	859.40	+
38	FLOOR PANEL	Revis	1025.30	+
39	FLOOR PANEL TOP BOARD	Del d	580.70	+
40	FLOOR PANEL TOP SIDE BOARD @159.20	New	318.40	+
41	FLOOR PANEL INNER GARNISH	New	349.40	+
42	SPARE TYRE CARRIER		322.90	+
43	REAR EXHAUST PIPE	Not	791.30	+
44	REAR EXHAUST PIPE MOUNTING	New	38.40	+
45	REAR EXHAUST PIPE GASKET		32.10	+



less	25%	12344.50	25%	
		37033.50		

SPECIAL NETT ITEMS

1 REAR NUMBER PLATE	<i>3 hrs</i>	30.00	/
2 REAR NUMBER PLATE HOLDER		30.00	/
3 REAR BUMPER CLIPS	<i>nr</i>	30.00	/
4 REVERSE SENSOR	<i>2 hrs</i>	<del>280.00</del>	<i>200</i>
5 REAR END PANEL SEALANT	<i>nr</i>	60.00	/
6 REAR END PANEL TOP GARNISH CLIPS	<i>nr</i>	20.00	/
7 TAILGATE INNER TRIM BOARD CLIPS	<i>nr</i>	30.00	/
8 TAILGATE INNER SIDE TRIM BOARD CLIPS	<i>nr</i>	40.00	/
9 TAILGATE INNER TOP BOARD CLIPS	<i>nr</i>	10.00	<i>x</i>
10 TAILGATE GLASS SEALANT		60.00	/
11 TAILGATE GLASS SOLAR FILM	<i>3 hrs</i>	<del>280.00</del>	<i>200</i>
12 REAR CAMERA	<i>2 hrs</i>	<del>480.00</del>	<i>380</i>
13 REAR FENDER INNER TRIM BOARD CLIPS		60.00	/
14 REAR FENDER INNER UPPER TRIM BOARD CLIPS	<i>3 hrs</i>	40.00	/
15 REAR FENDER INNER SHIELD CLIPS	<i>nr</i>	40.00	/
16 REAR LH FENDER GLASS SEALANT	<i>nr</i>	40.00	/
17 FLOOR PANEL INSULATION PAD	<i>nr</i>	280.00	<i>x</i>
18 FRONT NUMBER PLATE	<i>3 hrs</i>	30.00	/
19 FRONT NUMBER PLATE HOLDER		30.00	/
20 FRONT BUMPER CLIPS	<i>3 hrs</i>	30.00	/
21 FRONT BUMPER UNDERCOVER CLIPS		30.00	/
22 FRONT GRILLE CLIPS	<i>3 hrs</i>	20.00	/
23 FRONT GRILLE TOP COVER CLIPS		20.00	/
24 BONNET INSULATOR CLIPS		30.00	/
25 AIR CON CONDENSER SIDE GUIDE CLIPS	<i>nr</i>	20.00	/
26 RADIATOR COOLANT	<i>nr</i>	50.00	/
27 BATTERY	<i>2 hrs</i>	<del>200.00</del>	<i>150</i>
28 WIPER PANEL GARNISH CLIPS	<i>nr</i>	30.00	/
29 FRONT FENDER INNER SHIELD CLIPS	<i>nr</i>	<del>60.00</del>	<i>30</i>
30 FIREWALL INSULATION	<i>1 hr</i>	<del>300.00</del>	<i>200</i>
Total Parts		2660.00	

Front Windscreen Sealant 60 ✓  
 FRP Bracket nr 20 ✓  
 Front Windscreen Soler Film. ~~280~~ 200.  
 nr

2210

# AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY@KAKI BUKIT  
SINGAPORE 417883

Page No. 2

Vehicle No. <sup>36550</sup>SMK365D

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
	<u>LABOUR</u>		
1	PANEL BEATING	<del>4500.00</del>	3000
2	SPRAY PAINTING	<del>3500.00</del>	2800
3	WIRING	<del>150.00</del>	100
4	TO APPLY TUFF COAT	<del>250.00</del>	200
5	TO REMOVE UPHOLSTERY	<del>150.00</del>	120
6	TO TRANSFER TAILGATE FITTINGS	<del>150.00</del>	80
7	TO REPLACE TAILGATE GLASS	<del>180.00</del>	120
8	TO REPLACE REAR FENDER GLASS	<del>100.00</del>	40
9	TO REMOVE REVERSE SENSOR	<del>100.00</del>	50
10	TO REMOVE REAR CAMERA	<del>100.00</del>	50
11	TO REMOVE FUEL TANK	<del>150.00</del>	80
12	TO TRANSFER REAR DOOR FITTINGS	<del>150.00</del>	80
13	TO REMOVE REAR & CENTRE EXHAUST PIPES	300.00	X
14	TO VACCUM GLASS FRAGMENTS & TO CLEAN UP INTERIOR	<del>120.00</del>	80
15	TO REMOVE CONDENSER & TO TOP UP AIR CON GAS	<del>120.00</del>	60
16	TO REMOVE RADIATOR & TO TOP UP COOLANT	<del>120.00</del>	60
17	TO LIFT UP ENGINE & GEARBOX TO FACILITATE REPAIRS	380.00	X
18	TOWING FEES	60.00	✓
	Labour Total :	10580.00	
	TOTAL (PARTS & LABOUR):	50273.50	

6920

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

total: 37584.70

1/5: 30K.

24 Days