

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Alfred Toh

Date: 18 Oct 2022

Preliminary Advice

Vehicle No	: GBK7775U	Accident Date	: 10/10/2022
Make	: TOYOTA HIACE	Policy No.	: DMCVSNW00138232101
Assignment Date	: 14/10/2022	Excess	: S\$1,500.00
Date of Inspection	: 17/10/2022	Est. Duration of Repair	: 6
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,480.43
Revised Amount	:S\$	4,485.18
Check Items (Estimated)	:S\$	2,770.00
Total	:S\$	7,255.18

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 87,000.00
COE / PARF Rebate	:S\$ 21,789.00

Salvage Value	:S\$
Margin for Repair	:S\$ 65,211.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Our surveyor would like to check if the aftermarket front bonnet and front bumper covered under the policy and all the tyres of the insured vehicle were found to be in good serviceable condition with remaining tread depth of approximately 6mm for front tyre and 4mm for rear tyre. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.