

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22010243/AVE2**Date:** 22/02/2023**REFERENCE**

Insured/Claimant: CHEONG HON CHOY, DARREN

Policy No: 2070172452-01

Date of Loss: 18/09/2022

Nature of Claim: OD

Claim No: 0288750460SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SCN3909A**

Make & Model: AUDI A5, 2.0 SPORTBACK (A)

Engine No: DEM025271

Reg. Date: 14/12/2020 (Man. Year: 2020)

Chassis No: WAUZZZF50MA000615

Colour: White

Odometer: 12287 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$190,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 245/40 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,132.00	9,974.00	4,158.00	29.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	3,022.00	2,350.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,504.00	12,996.00	6,508.00	33.37
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	17,904.00	11,396.00	6,508.00	36.35
+ GST 8.00/8.00% (S\$)	1,432.32	911.68	520.64	36.35
Nett Amount (S\$)	19,336.32	12,307.68	7,028.64	36.35

INSPECTION

Date of Assignment: 17/10/2022

Date Inspected: 12/10/2022

Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Torn	293.00 FS	*234.00 FS
3	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	72.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cut	151.00 FS	*120.40 FS
5	1		*FRONT BUMPER TRIM - LH	Not Necessary	54.00 FS	*- FS
6	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	41.00 FS	*- FS
7	1		*FRONT FENDER - LH	Buckled	1,189.00 FS	*951.20 FS
8	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
9	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	83.00 FS	*- FS
10	1		*FRONT FENDER BRACKET - LH REAR	Not Necessary	65.00 FS	*- FS
11	2		*FRONT FENDER BRACKET - LH CENTER	Not Necessary	79.00 FS	*- FS
12	1		*FRONT FENDER BRACE - LH	Not Necessary	132.00 FS	*- FS
13	10		*FRONT FENDER RIVET	Not Necessary	38.00 FS	*- FS
14	1		*FRONT FENDER LEDGE COVER - SHORT	Not Necessary	18.00 FS	*- FS
15	1		*FRONT FENDER LEDGE COVER - LONG	Not Necessary	40.00 FS	*- FS
16	1		*FRONT FENDER CHROME TRIM - LH	Necessary	171.00 FS	*136.40 FS
17	1		*FRONT WHEEL SPOILER	Not Necessary	82.00 FS	*- FS
18	1		*FRONT WHEEL SPOILER STONE CHIP GUARD - LH	Not Necessary	57.00 FS	*- FS
19	1		*HEADLIGHT - LH	Cut	8,172.00 FS	*6,537.60 FS
20	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	266.00 FS	*- FS
21	1		*FRONT PARKING AID SENSOR - SIDE	Not Necessary	266.00 FS	*- FS
22	6		*FRONT PARKING AID SEAL RING	Not Necessary	15.00 FS	*- FS
23	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					14,132.00	9,974.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	1,900.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,372.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >