



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNC 3328D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	CNC BADGE (SN)	NOT NECESSARY	80.00	-
1	COVER-RR BUMPER (SN)	BROKEN	651.00	651.00
1	COVER-RR BUMPER LWR (SN)	BROKEN	241.00	241.00
1	COVER-RR BUMPER FOG LAMP, LH (SN)	NOT NECESSARY	88.00	-
1	COVER-RR BUMPER FOG LAMP, RH (SN)	NOT NECESSARY	88.00	-
1	ULTRASONIC SENSOR ASSY-BWS (SN)	NOT NECESSARY	163.00	-
1	BEAM-RR BUMPER (SN)	NOT NECESSARY	318.00	-
1	LOGO ASSY-KIA SUB (SN)	NOT NECESSARY	32.00	-
1	EMBLEM-GT LINE (SN)	NOT NECESSARY	45.00	-
			1,806.00	912.00
<b><u>LABOUR</u></b>				
	REPLACE THE REAR BUMPER, REPAIR REAR BOOTLID & REPLACE ACCIDENT DAMAGE PARTS.		1,920.00	640.00
	SPRAY REAR BUMPER, REAR BOOTLID, REAR END PANEL, AND BOTH REAR FENDER PANEL.		2,750.00	550.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00	280.00
	CHECK ELECTRICAL WIRING AND COMPONENT.		100.00	100.00
	REMOVE & INSTALL INCLUDING TEST SENSOR.		100.00	80.00
	ANTI RUST PROOFING FOR PAINT WORK.	NOT NECESSARY	80.00	-
			5,230.00	1,650.00
<b>GRAND TOTAL</b>			<b>7,036.00</b>	<b>2,562.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,562.00</b>

Report Ref No. CS/SMR22010254/Evy3e2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.