

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22010257/TVY3E2**Date:** 20/01/2023REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00155252201
Claimant Vehicle No :	SMH3789S	Insured Vehicle No :	SLQ7522H
Date of Loss:	14/10/2022	Nature of Claim: TP	Claim No: SNM22D207358/C02/KHONGLH

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH3789S	Engine No:	2ZR0C15950
Make & Model:	TOYOTA NOAH, 1.8 (A)	Chassis No:	ZWR800337770
Reg. Date:	21/01/2019 (Man. Year: 2018)	Odometer:	110892 km
Colour:	White	Engine Capacity:	1797 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,713.82	6,302.75	7,411.07	54.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	1,630.00	3,270.00	66.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,613.82	7,932.75	10,681.07	57.38
Approved Total (Overridden) (S\$)		6,300.00		
Nett Amount (S\$)	18,613.82	6,300.00	12,313.82	66.15

INSPECTION

Date of Assignment:	09/12/2022	
Date Inspected:	19/10/2022	Inspected At: HD Perfect Autowork Pte Ltd (HQ) 8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Jan 2023)
Parts: M1-MPV	TOYOTA NOAH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMH3789S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,339.31 FL	*986.00 FL
2	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	28.10 FL	*- FL
3	2		*REAR BUMPER REFLECTOR	Not Necessary	251.20 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER (FRONT)	Not Necessary	291.60 FL	*- FL
5	1		*TAILGATE	Bent	1,812.70 FL	*1,812.70 FL
6	1		*TAIL GATE EMBLEM HYBRID SYNERGY DRIVE	Necessary	75.20 FL	*75.20 FL
7	2		*TAILGATE STOPPER	Not Necessary	57.20 FL	*- FL
8	1		*TAILGATE INNER LOCK	Bent	452.10 FL	*452.10 FL
9	1		*TAILGATE LOWER LOCK	Not Necessary	36.70 FL	*- FL
10	1		*TAILGATE BUZZER	Not Necessary	96.30 FL	*- FL
11	1		*TAILGATE DETECTOR	Cracked	175.20 FL	*175.20 FL
12	1		*TAILGATE DETECTOR WIRE HARNESS	Not Necessary	287.30 FL	*- FL
13	1		*TAILGATE INNER TRIM	Cracked	580.30 FL	*580.30 FL
14	1		*TAILGATE INNER HOLDER	Not Necessary	65.00 FL	*- FL
15	1		*TAILGATE WEATHER STRIP	Cut	375.10 FL	*375.10 FL
16	1		*TAILGATE WINDSCREEN GLASS C/W MOULDING	Not Necessary	1,198.70 FL	*- FL
17	2		*TAIL LAMP LOWER GARNISH	Not Necessary	357.60 FL	*- FL
18	2		*TAIL LAMP LOWER GARNISH RETAINER	Not Necessary	321.40 FL	*- FL
19	1		*REAR FENDER INNER TRIM	O/S NotNecessary/N/S Deformed	1,813.02 FL	*685.00 FL
20	2		*REAR FENDER COWLING	Not Necessary	237.40 FL	*- FL
21	1		*REAR END PANEL C/W END EXTEND PANEL	Bent	762.20 FL	*762.20 FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	168.20 FL	*168.20 FL
23	1		*REAR FLOOR MAT	Not Necessary	685.10 FL	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Deformed	1,165.50 FL	*1,105.00 FL
25	1		*JACK COVER GARNISH	Not Necessary	186.00 FL	*- FL
26	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
27	1		*SET REAR BUMPER DIFFUSER (SPECIAL TYPE)	Cracked	1,800.00 FS	*600.00 FS
28	1		*SET TAIL LAMP LOWER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
29	1		*SET TAILGATE OUTER MOULDING CLIP	Not Necessary	40.00 FS	*- FS
30	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
31	1		*SET TAILGATE TOP INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
32	1		*SET TAILGATE SIDE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
33	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*30.00 FS
35	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	550.00 FS	*- FS
36	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
37	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
38	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
39	1		*REAR END PANEL INSULATION SEAL	Not Necessary	150.00 FS	*- FS
40	1		*SET JACK COVER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
41	1		*JACK	Not Necessary	150.00 FS	*- FS
42	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
43	2		*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	16,918.43	8,097.00
					- List Item Discount on L Items 25.00/25.00% (\$)	3,204.61	1,794.25
					Total Parts (\$)	13,713.82	6,302.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	New	1,600.00	600.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	700.00
3	TUFF COAT	New	250.00	30.00
4	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	180.00	60.00
5	REMOVE AND REFIX REAR AIRCON BLOWER MOTOR	New	350.00	0.00
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	30.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	30.00
8	REAR CHASSIS ALIGNMENT	New	250.00	0.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	New	150.00	120.00
10	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
12	REMOVE AND REFIX FUEL TANK TO FACILIATE FLOOR PANEL REPLACEMENT	New	80.00	0.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
14	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	New	80.00	0.00
Gross Labour Cost (\$)			4,900.00	1,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >