



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## OPINION ON REPAIR COST FOR VEHICLE NO. SJE 3250E

Qty	Description of Parts	Condition	Recommended (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>		
1	FRT LH DOOR	TO REPAIR SEE LABOUR	-
1	FRT LH DOOR GARNISH	BENT	100.00
1	FRT LH SIDE LAMP	TO REPAIR SEE LABOUR	-
1	FRT LH FENDER	TO REPAIR SEE LABOUR	-
1	FRT LH FENDER EMBLEM	NECESSARY	55.00
			155.00
	<b><u>LABOUR</u></b>		
	REPLACING ACCIDENT DAMAGED PARTS, KNOCK/JACK & STRAIGHTEN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRT LH DOOR, FRT LH SIDE LAMP AND FRT LH FENDER.		300.00
	SPRAY PAINTING ACCIDENT AFFECTED AREAS.		500.00
	CHECKING ELECTRICAL WIRING & LIGHTING SYSTEM FOR PROPER FUNCTION.		30.00
			830.00
<b>GRAND TOTAL</b>			<b>985.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>800.00</b>

Report Ref No. CS3/SPF22010263/Gvy3m4

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$800-\$1,300**

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.