

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22010264/Gwy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	31/10/2022		
	ATTN: KITTY TEO			Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHC 5795X	Veh. Inspected	l	SMZ 133J	
	Policy No.	VFX/P2413997	Coverage (\$)		0.00	
	Claim No.	S2M04CQO	Excess (\$)		0.00	
	Assign From	KITTY TEO	Assign Date		17/10/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ GLA180	c.c		1595	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	WDC1569422J591954	Colour		WHITE	
	Odometer	70935 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40ZR19	MICHELIN		6 mm	
	L/H Front Tyre	245/40ZR19	MICHELIN		6 mm	
	R/H Rear Tyre	245/40ZR19	MICHELIN		6 mm	
	L/H Rear Tyre	245/40ZR19	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION.					
5.	. General Information					
	Accident Date	12/10/2022	Inspect Date /	Time	18/10/2022 (05:30 PM)	
	Survey held at	Survey held at GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$12,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days					

Report Ref No. CS3/ASM22010264/Gwy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor