

ASS. REC. BY:

REF:

A15/22010271kq43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Yr Regn: 12, 17

c.c. 1797

A/C: Insured / Std / NI / NA

T/Radio: Insured / Std / NI / NA

24X10 2087417

F: Triangle 215/60R17

R: Tourada

Rear

R/Bal.

L/Bal.

D.O.I.

7/11/2022

Date/Time, File Pass to?

1) 22/11/2022

Date/Time, File Return to?

2)

Prell. Report

Final Report

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech Invs (\$)

Weekend (\$)

Survey Fee:

Transportation

S + RS \$

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.F. (\$)

Tp

1000

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLV 4397 X
Make : Toyota C-HR
Year : 2017

*Not Withheld
61 Supp \$10000
Resurvey After Paint
2 days*

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear top bumper	<i>610-90</i>	<i>Bu</i> \$885.60 <i>od/wr</i> ✓
1 pc	Rear lower bumper		\$455.70 ✓
1 pc	Rear bumper reinforcement		\$483.20 X
2 pcs	Rear bumper side retainer		<i>75.10</i> <i>Bu</i> \$150.20 X
			\$1,974.70
		Less 25 %	\$493.67
			\$1,481.03

S Nett

1 pc	Rear reverse sensor	<i>bu</i> \$200.00 X
15 pcs	Rear bumper clip	<i>na</i> \$30.00 ✓

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.	<i>2000</i> \$500.00
To putty & spray paint on accident affected portion	<i>2200</i> \$550.00
Check and reconnect wiring	<i>na</i> \$20.00 X
	Total \$2,781.03

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: