

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/HLA22010278/UQY3M4**Date:** 27/10/2022REFERENCE

Handling Insurer:	HL Assurance Pte Ltd	Policy No:	MP310428
<b>Claimant Vehicle No :</b>	GBH7056C	<b>Insured Vehicle No :</b>	SLD6148E
Date of Loss:	12/10/2022	Nature of Claim:	TP
		Claim No:	MPC03760

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBH7056C</b>	Engine No:	1KD2814928
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y50K211198
Reg. Date:	03/09/2018 (Man. Year: 2018)	Odometer:	119525 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/70 R15	Rear Tyre Size:	155 R12 (D/D)
Front Left Side:	Firestone 7 mm	Rear Left Side:	Dunlop 6/6 mm
Front Right Side:	Firestone 7 mm	Rear Right Side:	Dunlop 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,396.93	2,550.66	2,846.27	52.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,990.00	1,460.00	530.00	26.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,386.93</b>	<b>4,010.66</b>	<b>3,376.27</b>	<b>45.71</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,386.93</b>	<b>3,200.00</b>	<b>4,186.93</b>	<b>56.68</b>

INSPECTION

Date of Assignment:	17/10/2022		
Date Inspected:	18/10/2022	Inspected At:	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 27 Oct 2022)	
<b>Parts:</b>	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GBH7056C)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,582.60 FL	*1,582.60 FL
2	1		*TAILGATE STICKER TOYOTA	Necessary	190.60 FL	*190.60 FL
3	1		*TAILGATE STICKER DYNA	Not Necessary	58.60 FL	*- FL
4	1		*TAILGATE LOWER MEMBER	Bent	495.50 FL	*495.50 FL
5	4		*TAILGATE HINGES @\$65.50	Not Necessary	262.00 FL	*- FL
6	1		*TAILGATE STOPPER -RH	Torn	48.20 FL	*48.20 FL
7	1		*TAILGATE STOPPER BRACKET -RH	Bent	110.50 FL	*110.50 FL
8	1		*TAILLAMP -RH	Cracked	291.33 FL	*291.33 FL
9	1		*TAILLAMP BRACKET	Repair	258.10 FL	*- FL
10	1		*SIDEGATE -RH	Not Necessary	1,865.90 FL	*- FL
11	1		*SIDEGATE LOCK HINGES -RH	Bent	241.50 FL	*241.50 FL
12	1		*SIDEGATE LOWER MEMBER	Repair	495.50 FL	*- FL
13	1		*REAR EXHAUST PIPE	Repair	481.60 FL	*- FL
14	1		*REAR LICENCE PLATE PANEL	Bent	120.65 FL	*120.65 FL
15	1		*REAR NUMBER PLATE	Bent	40.00 FS	*20.00 FS
16	1		*REAR STICKER 70KM/H	Necessary	10.00 FS	*10.00 FS
17	1		*REAR STICKER 13PAX	Necessary	10.00 FS	*10.00 FS
18	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
19	1		*REAR STEP BRACKET	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>7,022.58</b>	<b>3,320.88</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	1,625.65	770.22
<b>Total Parts (S\$)</b>	<b>5,396.93</b>	<b>2,550.66</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK REAR ELECTRICAL WIRING	New	50.00	20.00
2	TO REMOVE, REPLACE REVERSE SENSOR	New	60.00	40.00
3	TO TUFF KOTE	New	80.00	50.00
4	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	New	900.00	550.00
5	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	New	900.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,990.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >