

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No.200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 620457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2000944016-01	Date of Loss:	11/10/2022
Vehicle Reg. No.:	SMU772R	Driveable?	
Driver Age/Info:	27 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	MOHAMMAD TAUFIQ BIN ROSLI	Contact No:	+6592299426
Driver:	MOHAMMAD TAUFIQ BIN ROSLI		

Make/Model:	VOLKSWAGEN SCIROCCO, 1.4 L (A)	Vehicle Reg. Date:	02/08/2010
Vehicle Colour:	GREEN	Chassis No:	WVWZZZ13ZAV450758
Engine No:	CAV199257		
Odometer:	217578 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	20

Description of Accident/Loss: ON 11/10/2022 @
Present Location: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

	Amount
COST OF CLAIMS	21,375.00
Parts	0.00
Miscellaneous Items	4,430.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	25,805.00
+ GST 7.00% (\$\$)	1,806.35
Nett Amount (\$\$)	27,611.35

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Oct 2022)
 144 VOLKSWAGEN SCIROCCO 1.4 L (A) (Catalogue Merimen Singapore 1.0)
 Repairer's (Price-denominated Standard List)
 At Code: (Unsubmitted, no print-code for SMU772R)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER / BR ? X nn	0.00	0.00	*700.00F ✓
2	2		*FRT BUMPER RETAINER	0.00	0.00	*80.00F
3	10		*FRT BUMPER CLIPS / MK	0.00	0.00	*50.00F 30 ✓
4	1		*FRT SIGNAL LAMP LH X nn	0.00	0.00	*90.00F
5	2		*FRT SIGNAL LAMP COVER X nn	0.00	0.00	*120.00F
6	2		*FRT FENDER / DD	0.00	0.00	*1,000.00F ✓
7	2		*FRT FENDER INNERSHIELD / Tn	0.00	0.00	*200.00F ✓
8	20		*FRT FENDER INNERSHIELD CLIPS / MK	0.00	0.00	*100.00F 50 ✓
9	2 + 2		*FRT HEADLAMP (RH) - CVI (LH) BR	0.00	0.00	*1,600.00F ✓
10	1		*FRT DOOR RH - DD	0.00	0.00	*1,200.00F ✓
11	1		*FRT DOOR LOCK RH ? X nn	0.00	0.00	*250.00F
12	1		*FRT DOOR OUTER HANDLE RH - CVI	0.00	0.00	*180.00F ✓
13	1		*FRT DOOR OUTER HANDLE CAP RH / MK	0.00	0.00	*30.00F ✓
14	1		*FRT DOOR GLASS RH - BR	0.00	0.00	*200.00F ✓
15	1		*FRT DOOR GLASS REGULATOR RH ? X nn	0.00	0.00	*220.00F
16	1		*FRT DOOR GLASS REGULATOR MOTOR RH ? X nn	0.00	0.00	*580.00F
17	1		*FRT DOOR GLASS OUTER TOP MOULDING RH - CUT	0.00	0.00	*160.00F ✓
18	1		*FRT DOOR GLASS OUTER MOULDING RH - CVI	0.00	0.00	*140.00F ✓
19	1		*FRT DOOR GLASS INNER MOULDING RH - CVI	0.00	0.00	*170.00F ✓
20	1		*FRT DOOR GLASS UPPER INNER SEAL RH - MK	0.00	0.00	*180.00F ✓
21	1		*FRT DOOR GLASS LOWER INNER SEAL RH - MK	0.00	0.00	*120.00F ✓
22	1		*FRT DOOR INNER TRIM BOARD RH / Tn	0.00	0.00	*1,200.00F ✓
23	1		*FRT SIDE MIRROR ASSY RH - BR	0.00	0.00	*350.00F ✓
24	1		*FRT SIDE MIRROR COVER RH - MK	0.00	0.00	*150.00F ✓
25	1		*FRT SIDE MIRROR INNER SEAL RH / Tn	0.00	0.00	*120.00F ✓
26	1		*REAR FENDER RH - DD	0.00	0.00	*850.00F ✓
27	1		*REAR FENDER INNER SHIELD RH / Tn	0.00	0.00	*120.00F ✓
28	10		*REAR FENDER INNER SHIELD CLIPS - MK	0.00	0.00	*50.00F 25 ✓
29	1		*REAR BUMPER - BR	0.00	0.00	*600.00F ✓
30	1		*REAR BUMPER RETAINER RH - BR	0.00	0.00	*35.00F ✓
31	10		*REAR BUMPER CLIPS - MK	0.00	0.00	*50.00F 30 ✓
32	1		*REAR TAILLAMP RH - CVI	0.00	0.00	*200.00F ✓
33	2		*FRT TYRE RIM / CVI (Front LH & Rear RH)	0.00	0.00	*2,400.00F 800 nett
34	1		*REAR TYRE RIM RH - CVI (Front LH) 80% Sof \$400	0.00	0.00	*1,200.00F 320 nett
35	2		*FRT ABSORBER ? X nn	0.00	0.00	*360.00F
36	2		*FRT ABSORBER TOP MOUNTING ? X nn	0.00	0.00	*170.00F
37	2		*FRT KNUCKLE ARM ? X nn	0.00	0.00	*1,000.00F
38	2		*FRT WHEEL HUB & BEARING ? X nn	0.00	0.00	*560.00F
39	2 - 1		*FRT LOWER CONTROL ARM ? BT (LH)	0.00	0.00	*440.00F 220 ✓
40	2 - 1		*FRT TIE ROD ? BT	0.00	0.00	*200.00F 100 ✓
41	2 - 1		*FRT TIE ROD END ? BT	0.00	0.00	*240.00F 120 ✓
42	1		*REAR QUARTER GLASS SEALANT - MK	0	0.00	*40.00FS 30 nett ✓
43	2		*FRT DRIVESHAFT ? X nn	0.00	0.00	*2,400.00F
44	1		*FRT CROSSMEMBER ? X nn	0.00	0.00	*850.00F
45	1		*FRT ANTI ROLL BAR ? X nn	0.00	0.00	*250.00F

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Part No.	Particulars	%Disc	%Depr	Amount
	*FRT STABILIZER LINK ¹ X nn	0.00	0.00	*170.00F
			Total Parts (S\$)	21,375.00

part. S=SpcNett.

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

10,080.00 + 1150.00 nett = 11,230.00

es on Miscellaneous Items
 new miscellaneous items selected.

Estimates on Labour
 Particulars

Labour Items	Lab.Type	Amount
1 TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New 1400	1,600.00
2 TO PUTTY & RESPRAY PAINTING ON AFFECTED AREA	New 1400	1,500.00
3 TO CHECK WIRING	New	50.00 ✓
4 TO TRANSFER FRT DOOR RH COMPONENTS	New	80.00 ✓
5 TO REMOVE & FIX REAR QUARTER GLASS	New ? 80	120.00
6 TO REPAIR & REPLACE UNDERCARRIAGE	New ? 200	750.00
7 TO REMOVE & REPLACE PETROL TANK	New ? X	100.00
8 TO DO WHEEL ALIGNMENT	New	80.00 ✓
9 TO DIAGNOSE & RESET SYSTEM, CLEARING ERROR IN SYSTEM	New 100	150.00
Gross Labour Cost (\$\$)		3390 4,430.00

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

14,620.00

L/S - 11,696.00
 = 11,700.00

Steve (LKK)
 18/10/22, 10:11
 OO M AL
 Expen - ?
 LIS
 My PL y
 14 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: