



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 9929E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR TAIL LAMP (RH)	CRACKED	998.00	585.00
1	REAR TAIL LAMP LOWER BRACKET (RH)	CRACKED	135.00	135.00
1	REAR BUMPER	BUCKLED	1,699.00	1,699.00
1	REAR BUMPER PARKTRONIC SENSOR (RH, OUTER)	SHORTED	270.00	270.00
1	REAR BUMPER TOWING COVER	SERVICEABLE	95.00	-
1	REAR BUMPER LIP	SERVICEABLE	351.00	-
1	REAR BUMPER SIDE RETAINER (RH)	DISTORTED	95.00	95.00
	LESS 10% DISCOUNT		-364.30	-278.40
			<b>3,278.70</b>	<b>2,505.60</b>
<b>LABOUR</b>				
	REMOVE AND TRANSFER REAR BUMPER NECESSARY ATTACHMENT SPART PART ITEMS. }		-	-
	REMOVE AND REFIT REAR TAIL LAMP (RH), REAR TAIL LAMP LOWER BRACKET (RH), REAR BUMPER, REAR BUMPER PARKTRONIC SENSOR (RH, OUTER), REAR BUMPER TOWING COVER, REAR BUMPER LIP, REAR BUMPER SIDE RETAINER (RH). }		-	-
	PANEL / BEATING REAR RH FENDER, HEAT / WELD / BEATING / PULL / STRAIGHTEN / ALIGN RERA CHASSIS FRAME BY CHASSIS ALIGNMENT JACK. }		900.00	300.00
	DIAGNOSTIC AND RESET REAR BUMPER PARKTRONIC SENSOR FAULT ERROR BY HHT.		100.00	60.00
	TO CHECK AND REFIT REAR TAIL LAMP WIRING HARNESS.		80.00	20.00
	UNDER COATING ON REAR DAMAGED PORTION.	NOT NECESSARY	200.00	-
	PUTTY / PRIMER APPLICATION, SPRAY PAINTING REAR RH FENDER, REAR BUMPER, REAR BUMPER PARKTRONIC SENSOR (RH, OUTER, REAR BUMPER TOWING COVER (PEARL WHITE).		1,000.00	440.00
			<b>2,280.00</b>	<b>820.00</b>
<b>GRAND TOTAL</b>			<b>5,558.70</b>	<b>3,325.60</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,650.00</b>
---	--	--	-----------------

Report Ref No. CS/FCI22010284/Kvy3e2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**