

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard, #04-01 Suntec Tower Three  
Singapore 038988

**Our File No:** CS/EGI22010288/EVY3E2**Date:** 20/12/2022REFERENCE

Insured/Claimant:	LIM KIM MOOI	Policy No:	DMPG22007098		
Date of Loss:	13/10/2022	Nature of Claim:	OD	Claim No:	CDMPG22002155

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKT8610B</b>		Engine No:	B1710894N20B20A
Make & Model:	BMW 528i, 2.0 AT ABS D/AB SR NAV HID (A)		Chassis No:	WBA5A52070D823656
Reg. Date:	29/05/2015 (Man. Year: 2014)		Odometer:	165213 km
Colour:	Brown			
Engine Capacity:	1997 cc			
Market Value/New Car Price:	S\$86,000.00			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,668.00	9,814.90	1,853.10	15.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,497.00	8,188.00	3,309.00	28.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,165.00</b>	<b>18,002.90</b>	<b>5,162.10</b>	<b>22.28</b>
<b>- Excess (S\$)</b>	700.00	700.00	0.00	0.00
<b>(S\$)</b>	22,465.00	17,302.90	5,162.10	22.98
<b>+ GST 7.00/7.00% (S\$)</b>	1,572.55	1,211.20	361.35	22.98
<b>Nett Amount (S\$)</b>	<b>24,037.55</b>	<b>18,514.10</b>	<b>5,523.45</b>	<b>22.98</b>

INSPECTION

Date of Assignment:	17/10/2022	
Date Inspected:	17/10/2022 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Dec 2022)
<b>Parts:</b>	143	BMW 528I 2.0 AT ABS D/AB SR NAV HID (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKT8610B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
2	1		*COVER	Not Necessary	70.20 FS	*- FS
3	1		*RADIATOR	Not Necessary	1,171.55 FS	*- FS
4	1		*BONNET	Dented	2,378.95 FS	*2,378.95 FS
5	1		*FRT SHOCK ABSORBER	Broken	72.50 FS	*72.50 FS
6	1		*FRT BUMPER PANEL PRIMED (PDC)	Broken	1,424.20 FS	*1,424.20 FS
7	1		*RH COVERING PRIMEND	Not Necessary	48.80 FS	*- FS
8	1		*SUPPORT	Necessary	21.75 FS	*4.90 FS
9	1		*FRT LH GRILLE (BASIS)	Not Necessary	144.35 FS	*- FS
10	1		*FRT RH GRILLE (BASIS)	Broken	144.35 FS	*144.35 FS
11	1		*BMW EMBLEM	Necessary	72.85 FS	*72.85 FS
12	1		*RH SUPPORT	Not Necessary	31.25 FS	*- FS
13	1		*CONNECTION TOP FRT	Not Necessary	240.00 FS	*- FS
14	1		*RH HEADLAMP SUPPORT	Bent	225.20 FS	*225.20 FS
15	1		*AIR DUCT	Broken	409.50 FS	*409.50 FS
16	10		*C CLIP NUT	Not Necessary	13.50 FS	*- FS
17	1		*CROSS BRACE FRT RH	Not Necessary	36.60 FS	*- FS
18	1		*RH BI XENON HEADLIGHT	Broken	2,702.85 FS	*2,702.85 FS
19	1		*CONDENSER AIR CONDITIONING	Bent	1,086.35 FS	*1,086.35 FS
20	4		*BLIND RIVET FLAT HEADED 6.5X14.3	Necessary	18.00 FS	*18.00 FS
21	1		*FRT RH 1 SIDE PANEL BRACKET	Bent	41.20 FS	*41.20 FS
22	1		*FRT BUMPER CARRIER	Bent	722.70 FS	*722.70 FS
23	1		*RH LEVER	Missing	6.95 FS	*6.95 FS
24	10		*BUMPER RIVET	Necessary	5.00 FS	*5.00 FS
25	1		*FRT RH LOCATOR SEAL	Broken	232.00 FS	*232.00 FS
26	1		*REPAIR KIT SOCKET HOUSING (12 POL)	Necessary	16.50 FS	*16.50 FS
27	1		*SET GASKET	Necessary	50.90 FS	*50.90 FS
28	1		*NOTICE SAFETY CATCH	Necessary	25.00 FS	*25.00 FS
29	1		*LABEL COOLANT	Necessary	25.00 FS	*25.00 FS
30	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>11,668.00</b>	<b>9,814.90</b>
--------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE BONNET, FRONT SUPPORT, FRONT BUMPER, MAKE GOOD FRONT RHS FENDER AND ATTACHMENTS	New	3,825.00	2,550.00
2	TO RESPRAY BONNET, FRONT BUMPER, FRONT RHS FENDER AND AFFECTED AREAS	New	3,221.00	3,059.00
3	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
4	TO CHECK ELECTRICAL	New	177.00	168.00
5	TO SUPPLY FRONT EMBOSS NUMBER PLATE	New	83.00	83.00
6	TO REPLACE RIGHT HEADLAMP	New	481.00	456.00
7	TO REPLACE RADIATOR ASSEMBLY, FAN HOUSING WITH FAN INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM AND CONDUCT CHECK FOR LEAK (ALL MODELS EXCEPT 7 SERIES)	New	826.00	0.00
8	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING VACUUM SYSTEM, TOP UP FREON GAS AND CONDUCT CHECK FOR LEAK (FOR ALL MODELS EXCEPT FOR 7 SERIES)	New	1,003.00	0.00
9	TO REMOVE AND INSTALL RADIATOR ASSEMBLY TO FACILITATE REPAIRS INCLUDE CONDUCTING PRESSURE TESTS, BLEED COOLING SYSTEM AND CHECKS FOR LEAK	New	639.00	639.00
10	TO REPLACE AIR CON CONDENSER AND AIR CON HOSE INCLUDING VACUUM SYSTEM, TOP UP FREON GAS AND CONDUCT CHECKS FOR LEAK	New	953.00	953.00
11	TO CARRY OUT BODY CAVITY PRESERVATION	New	112.00	112.00
<b>Gross Labour Cost (S\$)</b>			<b>11,497.00</b>	<b>8,188.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >